

From: [REDACTED] <[REDACTED]>

To: "jeffrey E." <jeevacation@gmail.com>

Cc: Rich Kahn <[REDACTED]>, Zorro Ranch <[REDACTED]>

Subject: ZM HWR Mech 1

Date: Sun, 09 Dec 2018 16:59:52 +0000

Attachments: ZM_HWR_Mech1_b.jpg; ZM_HTR_Mech1.JPG

FYI

Attached photo's for your reference

It appears a join in a Hot Water Return (HRW) Line in Mechanical Bay 1 Main house has failed developing a small leak.

I have placed an Emergency Service Call for Honeywell Service tech to review **Today**

They will try and isolate this zone if possible, if they can not, the Auxiliary Heating system will need to be shutdown completely.

Update will be forward after the tech has been on site and reviewed

[REDACTED]

Stanley, NM

LSJ-GSJ, USVI

[REDACTED]