

From: Jay Massar <[REDACTED]>

To: jeffrey E. <jeevacation@gmail.com>

CC: Eric Roth <[REDACTED]>

Subject: FW: G550 SN 5173 DIVAN ARM PARTITION

Date: Tue, 18 Sep 2018 18:05:00 +0000

Attachments: G550_SN_5173_DIVAN_ARM_PARTITION_WITH_U_CHANNEL.PNG

Inline-Images: image001.jpg; image002.jpg; image003.jpg; image004.jpg; image005.jpg; image006.jpg

Jeffrey,

Please review the attached drawing.


It is the same idea of a half bulkhead but when removed will have no attachment points visible on the arm.

Doing a full bulkhead poses a lot of issues with installing and removing it due to the curvature of the aircraft, the fact that it is beyond center and just the actual size of it.

Please provide feedback asap

Thank you

JAY MASSAR | OPERATIONS MGR





2221 Smithtown Avenue, Long Island MacArthur Airport, Ronkonkoma, New York 11779

From: Maurice Blibaum

Sent: Tuesday, September 18, 2018 1:05 PM

To: Eric Roth <[REDACTED]>

Cc: Jay Massar <[REDACTED]>

Subject: G550 SN 5173 DIVAN ARM PARTITION

MAURICE BLIBAUM | STRUCTURAL DESIGNER





2221 Smithtown Avenue, Long Island MacArthur Airport, Ronkonkoma, New York 11779

EFTA01022674