

**From:** Stephanie Remington <[REDACTED]>

**To:** J <jeevacation@gmail.com>, Richard Kahn <[REDACTED]>, Daphne Wallace <[REDACTED]>

**Subject:** Master Bath Mirrors

**Date:** Tue, 05 Feb 2019 14:58:21 +0000

---

I regret to share that when our carpenters removed the bracing today on the exterior bath mirrors, both mirrors fell. They were hung Sunday. The adhesive is supposed to stick immediately and is not supposed to require any bracing. Bracing was added for precaution. I believe the cause is that the sun beats on those mirrors all day and they are outside instead of in air conditioned space, rendering the adhesive unable to properly cure. Further, there is a very tiny crack in the top right corner of one of the interior mirrors. This, too, will need to be replaced.

I ordered a replacement for the interior 1/16" smaller as they were very difficult to fit due to the uneven tile that frames the space. This should remedy any pressure to the mirror going forward. I also ordered the exterior mirrors. The carpenters will prebuild a frame to hold the mirrors so that it can be fastened by both glue and with screws.

Stephanie Remington  
LSJE, LLC