

From: Larry Visoski <[REDACTED]>

To: Je vacation <jeevacation@gmail.com>

Subject: Update

Date: Wed, 06 Sep 2017 15:02:35 +0000

Inline-Images: IMG_2796.JPG; IMG_2802.JPG

Jeffrey

Low Trim Valves installed,

PAC Temp output constant at 35° full cold and full hot,.

Good fix,.

Still working #2 HF radio,.

We have Swapped the RT's and issue remained on #2 HF, Tech is speaking to tech ops in Savannah looking into fiber optics and other areas of HF,.

Question:

Do you want Eric to fabricate leather armrest covers like GIV?

Thx

Larry

Sent from my iPhone 

