

From: J <jeevacation@gmail.com>

To: Cashkim Bussue <[REDACTED]>

Cc: Richard Kahn <[REDACTED]>, Stephanie Remington <[REDACTED]>, michael glidden <[REDACTED]>

Subject: Re:

Date: Wed, 03 Apr 2019 19:31:15 +0000

MIKE , steph- please fix

On Wed, Apr 3, 2019 at 3:28 PM Cashkim Bussue <[REDACTED]> wrote:

Good day All,

Worthy of mention, attached are images of constant leakage underneath the master bedroom coming from the a/c vent. Following this further, below is a crack in the wall that holds some of the water when it drips.

Moreover, the guys and I used every possible liquid solution to remove any stains from the floor. To further illustrate, some of the stains are a matter of cement and paint hardened overtime and as a result, have difficulty moving. One of the method used in this process was power washing the entire floor. When the floor dries, all of those stains reappear.

Sent from my iPhone

--

please note

The information contained in this communication is confidential, may be attorney-client privileged, may constitute inside information, and is intended only for the use of the addressee. It is the property of JEE

Unauthorized use, disclosure or copying of this communication or any part thereof is strictly prohibited and may be unlawful. If you have received this communication in error, please notify us immediately by return e-mail or by e-mail to jeevacation@gmail.com, and destroy this communication and all copies thereof, including all attachments. copyright -all rights reserved