

**From:** Cashkim Bussue <[REDACTED]>

**To:** jeevacation@gmail.com

**Cc:** [REDACTED], [REDACTED], [REDACTED]

**Date:** Wed, 03 Apr 2019 19:27:57 +0000

**Inline-Images:** IMG\_6797.JPG; IMG\_6798.JPG; IMG\_6799.JPG

---

Good day All,

Worthy of mention, attached are images of constant leakage underneath the master bedroom coming from the a/c vent. Following this further, below is a crack in the wall that holds some of the water when it drips.

Moreover, the guys and I used every possible liquid solution to remove any stains from the floor. To further illustrate, some of the stains are a matter of cement and paint hardened overtime and as a result, have difficulty moving. One of the method used in this process was power washing the entire floor. When the floor dries, all of those stains reappear.

Sent from my iPhone 

