

From: Larry Visoski <[REDACTED]>
To: Je vacation <jeevacation@gmail.com>
Cc: Rich Kahn <[REDACTED]>
Subject: 550 interior
Date: Sun, 14 May 2017 17:56:59 +0000

Jeffrey

***cost savings from Eric's quote that are not required:

Crew seats: \$11,230 he's planning to paint them and New seat belts

1- all we need is new leather and Lamb seat cover in Gray, just like it is currently. It matches the Gray pedestal perfect. (Offer \$7,230). (\$4000 savings). I would like new softer foam for crew seats,, they are currently hard,.

2- control column boot (\$1,460) don't need it recovered. It's black leather and fine.

3-Floor covering cockpit (\$4,419) don't need, its Gray and looks fine.

If you didn't notice, the carpet in the cockpit is industrial carpet, it is not the same as the rest of the plane,. It's a Dark Gray. And has worn just fine, doesn't need to be changed.

4-Jump Seat \$8,425 is also quoted to be painted and new seat belts. We Just need New Leather and Lamb covering,. (Offer \$5000). (Savings \$3425)

5-Fwd Lav potty seat, (\$2,533) (looks fine, and is hidden from sight,) does this really need to be done? It's a neutral color, and looks fine.

6- Crew Privacy curtain,. I didn't know there was one installed,. I think Chevron removed it,. I did like the humor in this mornings Curtain with Bi-Planes,

All this adds up in savings: \$15,837 just cockpit alone.

Just my thoughts

Thx

Larry

COCKPIT AREA

208 Crew Seats \$11,230

The crew seats will be stripped of existing materials. The seats will be function-checked for proper operation. The customer will be notified of any additional costs required to repair or replace broken parts for approval. All exposed areas of the seat frames will be prepped and painted to color coordinate. The cushions, arm rests and related sections will be upholstered with customer- approved

material on the bottom and back cushions. The existing seat and shoulder harness assemblies will receive new color-coordinating webbing using the existing hardware.

211 Crew Privacy Curtain \$2,022

The crew privacy curtain will be replaced. Fabricate one (1) curtain with customer-approved material. The curtain will be retained through use of rare earth magnets and an embedded metal strip in the curtain to keep the curtain tight against the bulkhead.

209 Control Column Boots \$1,460

Fabricate and install new control column boots in leather to color coordinate.

225 Floor Covering (Cockpit) \$4,419

A 100% wool custom carpet will be fitted, cut and installed for the cockpit floor. All unfinished edges will be serged as required or aesthetically pleasing. The rudder heel plates will be cleaned and brushed or polished.

ENTRYWAY AREA

314 Forward Lavatory Potty Seat & Shroud \$2,533

The forward lavatory potty seat and surround(s) will be stripped and upholstered with customer- approved leather.

320 Jump Seat \$8,425

The pull out jump seat will be stripped of existing materials. The seat will be function-checked for proper operation. The customer will be notified of any additional costs required to repair or replace broken parts for approval. All exposed areas of the seat frame will be prepped and painted to color coordinate. The cushions, arm rests and related sections will be upholstered with customer- approved material. The existing seat and shoulder harness assemblies will receive new color- coordinated webbing using the existing hardware.

Sent from my iPad