

THE PALM BEACH GARAGE
MV - 86524
3215 S. Dixie Highway
West Palm Beach, FL 33405
phone: 561-833-6622 / fax: 561-833-6633

JEFFREY EPSTEIN
358 EL BRILLO
PALM BEACH, FL 33480

ESTIMATE # 150630002 06/30/15
2006 eng: 6.8L V8 PFI plate# EPST0002
BENTLEY vin# SCBLE37G26CX19439
ARNAGE RL

Page 1
mileage
31799

C# 818-8361

Customer Repair Instructions

Check A/C. Check engine light
Engine overheated
Check alarm. Check batteries.

→ **THERE WILL BE ADDITIONAL PARTS AND LABOR** ←

WE OFFER CLIMATE CONTROLLED INDOOR & OUTDOOR STORAGE.

GENERAL WORK				7844.68	Group Total
Au	1.00@	1065.11	1065.11 Aux. fan assembly	TERRY4 1.50hrs @137.50/hr	206.25
	1.00@	79.59	79.59 Drive belt	Car overheated. Pressure check.	
	1.00@	522.60	522.60 Water pump rem. new \$1500	Found coolant leak on left side of	
	1.00@	8.23	8.23 [REDACTED] o-ring	engine.	
	1.00@	11.70	11.70 Bypass gasket	TERRY4 24.00hrs @137.50/hr	3300.00
	1.00@	8.79	8.79 Lower [REDACTED] conn o-ring	Replace water pump assembly.	
	1.00@	1.09	1.09 Coolant pipe o-ring PQ30	Replace necessary o-rings and seals.	
	2.00@	15.47	30.94 O-ring	Replace belt.	
	1.00@	46.74	46.74 Timing cover gasket	Replace thermostat and seal.	
	1.00@	31.02	31.02 Timing cover strip	TERRY4 4.00hrs @137.50/hr	550.00
	1.00@	5.08	5.08 Oil tube/breather o-ring	Radiator electric fan assembly	
	1.00@	86.65	86.65 Front crankshaft seal	broken.	
	3.00@	15.93	47.79 Coolant pipe o-ring PQ2	Replace.	
	2.00@	2.76	5.52 O-ring PQ5	TERRY4 0.50hrs @137.50/hr	68.75
	2.00@	11.95	23.90 O-ring PQ2	Check batteries.	
	2.00@	2.42	4.84 Alum. washer	Replace left battery.	
	1.00@	31.65	31.65 Thermostat o-ring	Charge right battery-ok.	
	2.00@	37.19	74.38 Turbo oil gasket	TERRY4 1.50hrs @137.50/hr	206.25
	1.00@	1.09	1.09 Coolant pipe o-ring PQ30	A/C system.	
	3.00@	2.64	7.92 Washer PQ5	Service system.	
	2.00@	3.27	6.54 Washer PQ25	See next line. ←	
	2.00@	2.64	5.28 Washer	TERRY4	
	1.00@	31.02	31.02 Timing cover strip	A/C vent system.	
692MF	1.00@	229.43	229.43 Battery	Servo sticking, clicking sound in	
BATTERY TAX	1.00@	1.50	1.50 *	dash.	
	3.00@	23.00	69.00 Coolant	Must disassemble for estimate. \$???	
	2.00@	23.52	47.04 Pentosin	TERRY4	
	6.00@	1.50	9.00 Hose clamps	Alarm.	

06/30/15 11:46 AM

*** SEE NEXT PAGE ***

EFTA01089474

THE PALM BEACH GARAGE
MV - 86524
3215 S. Dixie Highway
West Palm Beach, FL 33405
phone: 561-833-6622 / fax: 561-833-6633

JEFFREY EPSTEIN
358 EL BRILLO
PALM BEACH, FL 33480

ESTIMATE # 150630002 06/30/15
2006 eng: 6.8L V8 PFI
BENTLEY vin# SCBLE37G26CX19439
ARNAGE RL

plate# EPST0002

Page 2
mileage
31799

C# 818-8361

1.00@	327.49	327.49 Thermostat	Trunk not fully closing. ?
1.00@	75.00	75.00 Shipping	Must disassemble for estimate.
1.00@	30.00	30.00 Freon	TERRY4 1.00hrs @137.50/hr 137.50
1.00@	12.95	12.95 A/C oil	TERRY4 2.00hrs @137.50/hr 275.00
1.00@	47.50	47.50 Oil filter	Service engine-lube
1.00@	2.15	2.15 Drain plug seal	
10.00@	10.99	109.90 Oil	
2.00@		Air filters??	
1.00@	2.50	2.50 Washer solvent	
Parts Sub-Total 3100.93			Labor Sub-Total 4743.75

WARRANTY: 6 MONTHS OR 6,000 MILES PARTS&LAB UNLESS OTHERWISE NOTED

06/30/15 11:46 AM

I, the Registered Owner, or Owner's representative, agree that I am receiving my repaired vehicle. After reviewing this repair order I agree that I requested the listed repairs and approve the associated parts needed to perform those repairs. Any questions I had regarding these repairs were answered to my satisfaction. To the best of my knowledge the repairs were performed satisfactorily.

I was advised that any items listed to the left, relating to safety issues of my vehicle, render my vehicle dangerous to drive now or in the near future.

PB Garage representative of Palm Beach Garage:

Vehicle Owner or representative: _____
Date: _____

PARTS	3100.93
LABOR	4743.75
ENVIRON/SHOP SUP	5.00
TAX	470.89
TOTAL WORK ORDER	8320.57

EFTA01089475







