

- = PREVIOUS FIX
 - = PROPOSED FIX BY LABONTE AND PILING PLUS
 - = PROPOSED ADDITIONAL REPAIR BY PILING PLUS 29 MANTA RAYS DRILL 18 WEEP HOLES WITH WELL POINTS
- WEEP HOLES + WELL POINTS ARE TO LET WATER FLOW OUT FROM BEHIND SEA WALL TO RELIEVE HYDROSTATIC PRESSURE. WELL POINTS ARE PLACED TO LET WATER OUT BUT KEEP SOIL IN

