

Aircraft Serial No 49063

Aircraft Model No 430

Code Action ATA Eng No	Event Name IRN / Task Number Comment	Identification Part Number / AD Serial Number / Ref	Required Every / in Tolerance	Event On A/C TTIS Event TSO Event TSN	Current Life Since O/H Since Install Since New	Due Airframe TTIS Date	Life Left Hours
Lubricate 12-5	25 Hour Lubrication	Pitch Link Universal BHT-430-MM-2	25.0 Hrs Mths +/- 2.5 hrs	1,274.9 Hrs 0.0 Hrs Hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,299.9 Hrs	25.0 Hrs
Lubricate 12-5	50 Hour Lubrication	Rotating Ring BHT-430-MM-2	50.0 Hrs Mths +/- 5 hrs	1,273.9 Hrs 0.0 Hrs Hrs	1.0 Hrs 1.0 Hrs 1.0 Hrs	1,323.9 Hrs	49.0 Hrs
Inspect 0500	50 Hourly Inspection 5-13	Bell 430 MM Griffin Helicopters SOM	50.0 Hrs 12 Mths +/- 5 hrs 1 mth	1,273.9 Hrs 0.0 Hrs Hrs	1.0 Hrs 1.0 Hrs 1.0 Hrs	1,323.9 Hrs 22 Aug 2011	49.0 Hrs Work in Progress
Inspect 5-40	Main Rotor Yoke Assembly	If Main Rotor Blades Removed N/A if not removed	50.0 Hrs Mths +/- 5 hrs	1,274.9 Hrs 0.0 Hrs Hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,324.9 Hrs	50.0 Hrs
Inspect 5-41, 5-42,	Installation Special Inspections	If Components Changed N/A if no components removed.	50.0 Hrs Mths +/- 5 hrs	1,274.9 Hrs 0.0 Hrs Hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,324.9 Hrs	50.0 Hrs
Verify 1	Turbine Wheel Max Overspeed	AD/AL250/90 CEB A-72-6054 Rev 2	50.0 Hrs Mths +/- 5 hrs	1,274.9 Hrs 0.0 Hrs Hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,324.9 Hrs	50.0 Hrs
Verify 2	Turbine Wheel Max Overspeed	AD/AL250/90 CEB A-72-6054 Rev 2	50.0 Hrs Mths +/- 5 hrs	1,274.9 Hrs 0.0 Hrs Hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,324.9 Hrs	50.0 Hrs
Inspect 0500	Swashplate Controls 5-28	Bell 430 MM Griffin Helicopters SOM	95.9 Hrs Mths +/- 10 hrs	1,233.1 Hrs 0.0 Hrs Hrs	41.8 Hrs 41.8 Hrs 41.8 Hrs	1,329.0 Hrs	54.1 Hrs
Inspect 0500 1	Engine 150 Hr Inspection	Table 603 RR 250-C40B MM	150.0 Hrs Mths +/- 15 hrs	1,223.6 Hrs 0.0 Hrs Hrs	51.3 Hrs 51.3 Hrs 51.3 Hrs	1,373.6 Hrs	98.7 Hrs
Inspect 0500 2	Engine 150 Hr Inspection	Table 603 RR 250-C40B MM	150.0 Hrs Mths +/- 15 hrs	1,223.6 Hrs 0.0 Hrs Hrs	51.3 Hrs 51.3 Hrs 51.3 Hrs	1,373.6 Hrs	98.7 Hrs
Lubricate 12-5	100 Hour Lubrication	Items 2, 4 and 9 BHT-430-MM-2	100.0 Hrs Mths +/- 10 hrs	1,273.9 Hrs 0.0 Hrs Hrs	1.0 Hrs 1.0 Hrs 1.0 Hrs	1,373.9 Hrs	99.0 Hrs
Inspect	Corrosion Inspection	Bell 430 MM	100.0 Hrs 3 Mths +/- 10 rs 3 days	1,274.9 Hrs 0.0 Hrs Hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,374.9 Hrs 28 Apr 2012	100.0 Hrs

Code Action ATA Eng No	Event Name IRN / Task Number Comment	Identification Part Number / AD Serial Number / Ref	Required Every / in Tolerance	Event On A/C TTIS Event TSO Event TSN	Current Life Since O/H Since Install Since New	Due Airframe TTIS Date	Life Left Hours
Inspect 0500 1	Engine 300 Hr Inspection	Table 604 RR 250-C40B MM	300.0 Hrs Mths +/- 30 hrs	1,082.4 Hrs 0.0 Hrs 0.0 Hrs	192.5 Hrs 192.5 Hrs 192.5 Hrs	1,382.4 Hrs	107.5 Hrs
Inspect 0500 2	Engine 300 Hr Inspection	Table 604 RR 250-C40B MM	300.0 Hrs Mths +/- 30 hrs	1,082.4 Hrs 0.0 Hrs 0.0 Hrs	192.5 Hrs 192.5 Hrs 192.5 Hrs	1,382.4 Hrs	107.5 Hrs
Inspect 0500	Swashplate Controls 5-29	Bell 430 MM Griffin Helicopters SOM	300.0 Hrs Mths +/- 30 hrs	1,083.0 Hrs 0.0 Hrs Hrs	191.9 Hrs 191.9 Hrs 191.9 Hrs	1,383.0 Hrs	108.1 Hrs
Check	Environmental Control Unit 12-1	Cooling Turbine BHT-430-MM-2	300.0 Hrs Mths +/- 30 hrs	1,083.0 Hrs 0.0 Hrs Hrs	191.9 Hrs 191.9 Hrs 191.9 Hrs	1,383.0 Hrs	108.1 Hrs
Change	Tail Rotor Gearbox 12-1	Oil Change BHT-430-MM-2	150.0 Hrs 6 Mths +/- 15 hrs 15 days	1,273.9 Hrs 0.0 Hrs Hrs	1.0 Hrs 1.0 Hrs 1.0 Hrs	1,423.9 Hrs 1 Jun 2011	149.0 Hrs Work in Progress
Inspect 0500	Directional Flight Control Bearing 5-14	ASB 430-10-45 REV A	150.0 Hrs 12 Mths +/- 15 hrs 1 mth	1,273.9 Hrs 0.0 Hrs Hrs	1.0 Hrs 1.0 Hrs 1.0 Hrs	1,423.9 Hrs 22 Aug 2011	149.0 Hrs Work in Progress
Inspect 0500	150 Hourly Inspection 5-14	Bell 430 MM Griffin Helicopters SOM	150.0 Hrs 12 Mths +/- 15 hrs 1 mth	1,274.9 Hrs 0.0 Hrs Hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,424.9 Hrs 28 Apr 2012	150.0 Hrs
Replace 0500	Maintenance Release	CASA 918 S/N A72393	165.0 Hrs 13 Mths 0 hrs 0 mths	1,274.9 Hrs 0.0 Hrs Hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,439.9 Hrs 28 May 2012	165.0 Hrs
Lubricate	300 Hour Lubrication 12-5	Items 3,5,6,10,11,12. BHT-430-MM-2	300.0 Hrs Mths +/- 30 hrs	1,156.3 Hrs 0.0 Hrs Hrs	118.6 Hrs 118.6 Hrs 118.6 Hrs	1,456.3 Hrs	181.4 Hrs
Overhaul 2	Compressor Bleed Valve	23005366 FF58734	1,500.0 Hrs Mths 0 hrs	398.7 Hrs 398.7 Hrs 398.7 Hrs	1,274.9 Hrs 876.2 Hrs 1,274.9 Hrs	1,500.0 Hrs	225.1 Hrs
Lubricate	300 Hr/12 Mth Lubrication 12-5	MLG & NLG Wheels BHT-430-MM-2	300.0 Hrs 12 Mths +/- 30 hrs 1 mth	1,273.9 Hrs 0.0 Hrs Hrs	1.0 Hrs 1.0 Hrs 1.0 Hrs	1,573.9 Hrs 2 Jun 2011	299.0 Hrs Work in Progress
Inspect 0500	IFR Radio Periodic	Pages 12 & 13 Griffin Helicopters SOM	300.0 Hrs 12 Mths 0 hrs 0 mths	1,273.9 Hrs 0.0 Hrs Hrs	1.0 Hrs 1.0 Hrs 1.0 Hrs	1,573.9 Hrs 22 Aug 2011	299.0 Hrs Work in Progress

Aircraft Serial No 49063

Aircraft Model No 430

Code Action ATA Eng No	Event Name IRN / Task Number Comment	Identification Part Number / AD Serial Number / Ref	Required Every / in Tolerance	Event On A/C TTIS Event TSO Event TSN	Current Life Since O/H Since Install Since New	Due Airframe TTIS Date	Life Left Hours
Inspect 0500	Pylon Fluid Mounts 5-32	Bell 430 MM Griffin Helicopters SOM	600.0 Hrs Mths +/- 60 hrs	1,051.0 Hrs 0.0 Hrs Hrs	223.9 Hrs 223.9 Hrs 223.9 Hrs	1,651.0 Hrs	376.1 Hrs
Overhaul 1	Rolls Royce Turbine Engine	250-C40B CAE-844134	1,750.0 Hrs Mths 0 hrs	398.7 Hrs 398.7 Hrs 398.7 Hrs	1,274.9 Hrs 876.2 Hrs 1,274.9 Hrs	1,750.0 Hrs	475.1 Hrs
Overhaul 2	Rolls Royce Turbine Engine	250-C40B CAE844136	1,750.0 Hrs Mths 0 hrs	398.7 Hrs 398.7 Hrs 398.7 Hrs	1,274.9 Hrs 876.2 Hrs 1,274.9 Hrs	1,750.0 Hrs	475.1 Hrs
Inspect 0500 1	Engine 1750 Hr Inspection	Table 605 RR 250-C40B MM	1,750.0 Hrs Mths +/- 60 hrs	Hrs Hrs Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	1,750.0 Hrs	475.1 Hrs
Inspect 0500 2	Engine 1750 Hr Inspection	Table 605 RR 250-C40B MM	1,750.0 Hrs Mths +/- 60 hrs	Hrs Hrs Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	1,750.0 Hrs	475.1 Hrs
Overhaul 2	Turbine Assembly	23063354 CAT44636	1,750.0 Hrs Mths 0 hrs	1,270.1 Hrs 1,266.3 Hrs 1,266.3 Hrs	1,271.1 Hrs 4.8 Hrs 1,271.1 Hrs	1,753.8 Hrs	478.9 Hrs
Replace 1	First Stage Wheel	23053299 X146181	1,775.0 Hrs Mths 0 hrs 0 cyc	398.7 Hrs 398.7 Hrs 398.7 Hrs	1,274.9 Hrs 876.2 Hrs 1,274.9 Hrs	1,775.0 Hrs	500.1 Hrs
Replace 1	Second Stage Wheel	23032280 HX128367	1,775.0 Hrs Mths 0 hrs 0 cyc	398.7 Hrs 398.7 Hrs 398.7 Hrs	1,274.9 Hrs 876.2 Hrs 1,274.9 Hrs	1,775.0 Hrs	500.1 Hrs
Replace 2	Second Stage Wheel	23032280 HX128595	1,775.0 Hrs Mths 0 hrs 0 cyc	1,270.1 Hrs 1,266.3 Hrs 1,266.3 Hrs	1,271.1 Hrs 4.8 Hrs 1,271.1 Hrs	1,778.8 Hrs	503.9 Hrs
Inspect 0500 1	Starter Generator 5-32	Bell 430 MM Griffin Helicopters SOM	600.0 Hrs Mths +/- 60 hrs	1,227.2 Hrs 0.0 Hrs Hrs	47.7 Hrs 47.7 Hrs 47.7 Hrs	1,827.2 Hrs	552.3 Hrs
Inspect 0500 2	Starter Generator 5-32	Bell 430 MM Griffin Helicopters SOM	600.0 Hrs Mths +/- 60 hrs	1,227.2 Hrs 0.0 Hrs Hrs	47.7 Hrs 47.7 Hrs 47.7 Hrs	1,827.2 Hrs	552.3 Hrs
Inspect 0500	Main Driveshaft 5-31	Bell 430 MM Griffin Helicopters SOM	600.0 Hrs 12 Mths +/- 60 hrs 1 mth	1,273.9 Hrs 0.0 Hrs Hrs	1.0 Hrs 1.0 Hrs 1.0 Hrs	1,873.9 Hrs 2 May 2011	599.0 Hrs

[Work Package Details](#)

[Work in Progress](#)

Aircraft Serial No 49063

Aircraft Model No 430

Code Action ATA Eng No	Event Name IRN / Task Number Comment	Identification Part Number / AD Serial Number / Ref	Required Every / in Tolerance	Event On A/C TTIS Event TSO Event TSN	Current Life Since O/H Since Install Since New	Due Airframe TTIS Date	Life Left Hours	Work Package Details
Inspect 0500	Tail Rotor Driveshaft 5-31	Bell 430 MM Griffin Helicopters SOM	600.0 Hrs 12 Mths +/- 60 hrs 1 mth	1,273.9 Hrs 0.0 Hrs Hrs	1.0 Hrs 1.0 Hrs 1.0 Hrs	1,873.9 Hrs 2 May 2011	599.0 Hrs	Work in Progress
Inspect 0500	Eng Fire Ext & Cartridge 5-30	Bell 430 MM Griffin Helicopters SOM	600.0 Hrs 6 Mths +/- 60 hrs 15 days	1,273.9 Hrs 0.0 Hrs Hrs	1.0 Hrs 1.0 Hrs 1.0 Hrs	1,873.9 Hrs 1 Jun 2011	599.0 Hrs	Work in Progress
Service 1	Engine Oil 12-1	BHT-430-MM-2	600.0 Hrs 6 Mths +/- 30 hrs 15 days	1,273.9 Hrs 0.0 Hrs Hrs	1.0 Hrs 1.0 Hrs 1.0 Hrs	1,873.9 Hrs 1 Jun 2011	599.0 Hrs	Work in Progress
Service 2	Engine Oil 12-1	BHT-430-MM-2	600.0 Hrs 6 Mths +/- 30 hrs 15 days	1,273.9 Hrs 0.0 Hrs Hrs	1.0 Hrs 1.0 Hrs 1.0 Hrs	1,873.9 Hrs 1 Jun 2011	599.0 Hrs	Work in Progress
Service	Nose Landing Gear 12-1	Centering Actuator BHT-430-MM-2	600.0 Hrs 6 Mths +/- 30 hrs 15 days	1,273.9 Hrs 0.0 Hrs Hrs	1.0 Hrs 1.0 Hrs 1.0 Hrs	1,873.9 Hrs 1 Jun 2011	599.0 Hrs	Work in Progress
Inspect 0500	600 Hourly Inspection 5-15	Bell 430 MM Griffin Helicopters SOM	600.0 Hrs 12 Mths +/- 60 hrs 1 mth	1,273.9 Hrs 0.0 Hrs Hrs	1.0 Hrs 1.0 Hrs 1.0 Hrs	1,873.9 Hrs 2 Jun 2011	599.0 Hrs	Work in Progress
Change	Transmission 12-1	Oil Change BHT-430-MM-2	600.0 Hrs 12 Mths +/- 60 hrs 1 mth	1,273.9 Hrs 0.0 Hrs Hrs	1.0 Hrs 1.0 Hrs 1.0 Hrs	1,873.9 Hrs 2 Jun 2011	599.0 Hrs	Work in Progress
Change	Hydraulic Reservoir 12-1	Oil Change BHT-430-MM-2	600.0 Hrs 12 Mths +/- 60 hrs 1 mth	1,273.9 Hrs 0.0 Hrs Hrs	1.0 Hrs 1.0 Hrs 1.0 Hrs	1,873.9 Hrs 2 Jun 2011	599.0 Hrs	Work in Progress
Lubricate	600 Hr / 12 Mth Lubrication 12-5	Driveshafts BHT-430-MM-2	600.0 Hrs 12 Mths +/- 60 hrs 1 mth	1,273.9 Hrs 0.0 Hrs Hrs	1.0 Hrs 1.0 Hrs 1.0 Hrs	1,873.9 Hrs 2 Jun 2011	599.0 Hrs	Work in Progress
Overhaul 1	Fuel Nozzle	23077067 1WP09785	2,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	2,000.0 Hrs	725.1 Hrs	
Overhaul 2	Fuel Nozzle	23077067 1WP09779	2,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	2,000.0 Hrs	725.1 Hrs	
Overhaul 1	Starter Generator	23081-018 99444	1,000.0 Hrs Mths	1,055.1 Hrs 0.0 Hrs	219.8 Hrs 219.8 Hrs	2,055.1 Hrs	780.2 Hrs	

Code Action ATA Eng No	Event Name IRN / Task Number Comment	Identification Part Number / AD Serial Number / Ref	Required Every / in Tolerance	Event On A/C TTIS Event TSO Event TSN	Current Life Since O/H Since Install Since New	Due Airframe TTIS Date	Life Left Hours
Overhaul	Starter Generator	23081-018 99317	1,000.0 Hrs Mths	1,055.1 Hrs 0.0 Hrs	219.8 Hrs 219.8 Hrs	2,055.1 Hrs	780.2 Hrs
2				1,055.1 Hrs	1,274.9 Hrs		
Change	Wheel Brake System 12-1	Oil Change BHT-430-MM-2	1,200.0 Hrs Mths +/- 60 hrs	1,083.0 Hrs 0.0 Hrs Hrs	191.9 Hrs 191.9 Hrs 191.9 Hrs	2,283.0 Hrs	1,008.1 Hrs
Change	Rotor Brake System 12-1	Oil Change BHT-430-MM-2	1,200.0 Hrs Mths +/- 60 hrs	1,083.0 Hrs 0.0 Hrs Hrs	191.9 Hrs 191.9 Hrs 191.9 Hrs	2,283.0 Hrs	1,008.1 Hrs
Overhaul	Compressor Bleed Valve	23073353 FF59372	1,500.0 Hrs Mths 0 hrs	804.1 Hrs 0.0 Hrs 804.1 Hrs	470.8 Hrs 470.8 Hrs 1,274.9 Hrs	2,304.1 Hrs	1,029.2 Hrs
1							
Inspect 0500 1	Hydraulic Pump Spline 5-33	Bell 430 MM Griffin Helicopters SOM	1,200.0 Hrs Mths +/- 60 hrs	1,195.4 Hrs 0.0 Hrs Hrs	79.5 Hrs 79.5 Hrs 79.5 Hrs	2,395.4 Hrs	1,120.5 Hrs
Inspect 0500 2	Hydraulic Pump Spline 5-33	Bell 430 MM Griffin Helicopters SOM	1,200.0 Hrs Mths +/- 60 hrs	1,195.4 Hrs 0.0 Hrs Hrs	79.5 Hrs 79.5 Hrs 79.5 Hrs	2,395.4 Hrs	1,120.5 Hrs
Inspect 0500	Swashplate Assembly 5-33	Bell 430 MM Griffin Helicopters SOM	1,200.0 Hrs Mths +/- 60 hrs	1,195.4 Hrs 0.0 Hrs Hrs	79.5 Hrs 79.5 Hrs 79.5 Hrs	2,395.4 Hrs	1,120.5 Hrs
Overhaul	Cyclic Servo	ASB-430-10-44 HR-460A	1,200.0 Hrs 12 Mths 0 hrs 0 mths	1,273.9 Hrs 0.0 Hrs 1,273.9 Hrs	1.0 Hrs 1.0 Hrs 1,274.9 Hrs	2,473.9 Hrs 22 Aug 2011	1,199.0 Hrs Work in Progress
Overhaul	Cyclic Servo	ASB-430-10-44 HR-461A	1,200.0 Hrs 12 Mths 0 hrs 0 mths	1,273.9 Hrs 0.0 Hrs 1,273.9 Hrs	1.0 Hrs 1.0 Hrs 1,274.9 Hrs	2,473.9 Hrs 22 Aug 2011	1,199.0 Hrs Work in Progress
Overhaul	Cyclic Servo	ASB-430-10-44 HR-462A	1,200.0 Hrs 12 Mths 0 hrs 0 mths	1,273.9 Hrs 0.0 Hrs 1,273.9 Hrs	1.0 Hrs 1.0 Hrs 1,274.9 Hrs	2,473.9 Hrs 22 Aug 2011	1,199.0 Hrs Work in Progress
Inspect	Main Rotor Yoke Assembly 5-34	430-010-101-101	2,500.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	2,500.0 Hrs	1,225.1 Hrs
Inspect	Main Rotor Blade Assembly 5-34	430-015-001-101	2,500.0 Hrs Mths +/- 60 hrs	0.0 Hrs 0.0 Hrs Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	2,500.0 Hrs	1,225.1 Hrs

Code Action ATA Eng No	Event Name IRN / Task Number Comment	Identification Part Number / AD Serial Number / Ref	Required Every / in Tolerance	Event On A/C TTIS Event TSO Event TSN	Current Life Since O/H Since Install Since New	Due Airframe TTIS Date	Life Left Hours
Inspect	Pylon Fluid Mount 5-34	430-310-200-107	2,500.0 Hrs Mths +/- 60 hrs	0.0 Hrs 0.0 Hrs Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	2,500.0 Hrs	1,225.1 Hrs
Inspect	Tail Rotor Gearbox Assembly 5-53	222-042-001-101 A-706	3,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	3,000.0 Hrs	1,725.1 Hrs
Overhaul	Oil Cooler Blower 5-53	230-365-001-101 1079	3,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	3,000.0 Hrs	1,725.1 Hrs
Overhaul	Oil Cooler Blower 5-53	230-365-001-101 1086	3,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	3,000.0 Hrs	1,725.1 Hrs
Replace 2	First Stage Wheel	23053299 X575880	1,775.0 Hrs Mths 0 hrs 0 cyc	1,270.1 Hrs 0.0 Hrs 0.0 Hrs	4.8 Hrs 4.8 Hrs 4.8 Hrs	3,045.1 Hrs	1,770.2 Hrs
Overhaul	Tail Rotor Hub 5-53	222-012-701-125 A-423	2,500.0 Hrs Mths 0 hrs	607.9 Hrs 0.0 Hrs 607.9 Hrs	667.0 Hrs 667.0 Hrs 1,274.9 Hrs	3,107.9 Hrs	1,833.0 Hrs
Overhaul 1	HMU	23078033 JGAMI0582	2,500.0 Hrs Mths 0 hrs	1,109.1 Hrs 167.5 Hrs 1,051.1 Hrs	333.3 Hrs 165.8 Hrs 1,216.9 Hrs	3,441.6 Hrs	2,166.7 Hrs
Inspect	Main Transmission Assembly 5-53	430-040-003-109 A-71	3,000.0 Hrs Mths 0 hrs	607.9 Hrs 0.0 Hrs 0.0 Hrs	667.0 Hrs 667.0 Hrs 667.0 Hrs	3,607.9 Hrs	2,333.0 Hrs
Overhaul 2	HMU	23078035 JGAMI0569	2,500.0 Hrs Mths 0 hrs	1,109.1 Hrs 0.0 Hrs 1,109.1 Hrs	165.8 Hrs 165.8 Hrs 1,274.9 Hrs	3,609.1 Hrs	2,334.2 Hrs
Overhaul	Hangar Assembly 5-53	222-044-003-113 BP-449	3,000.0 Hrs 36 Mths 0 hrs	1,251.7 Hrs 0.0 Hrs 1,251.7 Hrs	23.2 Hrs 23.2 Hrs 1,274.9 Hrs	4,251.7 Hrs 22 Nov 2012	2,976.8 Hrs
Overhaul	Hangar Assembly 5-53	222-044-003-113 BP-448	3,000.0 Hrs 36 Mths 0 hrs	1,251.7 Hrs 0.0 Hrs 1,251.7 Hrs	23.2 Hrs 23.2 Hrs 1,274.9 Hrs	4,251.7 Hrs 22 Nov 2012	2,976.8 Hrs
Overhaul	Hangar Assembly 5-53	222-044-003-115 49063	3,000.0 Hrs 36 Mths 0 hrs	1,251.7 Hrs 0.0 Hrs 1,251.7 Hrs	23.2 Hrs 23.2 Hrs 1,274.9 Hrs	4,251.7 Hrs 22 Nov 2012	2,976.8 Hrs

[Work Package Details](#)

Code Action ATA Eng No	Event Name IRN / Task Number Comment	Identification Part Number / AD Serial Number / Ref	Required Every / in Tolerance	Event On A/C TTIS Event TSO Event TSN	Current Life Since O/H Since Install Since New	Due Airframe TTIS Date	Life Left Hours	Work Package Details
Replace 1	Third Stage Wheel	6898663 HX93090	4,550.0 Hrs Mths 0 hrs 0 cyc	398.7 Hrs 398.7 Hrs 398.7 Hrs	1,274.9 Hrs 876.2 Hrs 1,274.9 Hrs	4,550.0 Hrs	3,275.1 Hrs	
Replace 1	Fourth Stage Wheel	23066744 HX75032	4,550.0 Hrs Mths 0 hrs 0 cyc	398.7 Hrs 398.7 Hrs 398.7 Hrs	1,274.9 Hrs 876.2 Hrs 1,274.9 Hrs	4,550.0 Hrs	3,275.1 Hrs	
Replace 2	Third Stage Wheel	6898663 HX93158	4,550.0 Hrs Mths 0 hrs 0 cyc	1,270.1 Hrs 1,266.3 Hrs 1,266.3 Hrs	1,271.1 Hrs 4.8 Hrs 1,271.1 Hrs	4,553.8 Hrs	3,278.9 Hrs	
Replace 2	Fourth Stage Wheel	23066744 HX75021	4,550.0 Hrs Mths 0 hrs 0 cyc	1,270.1 Hrs 1,266.3 Hrs 1,266.3 Hrs	1,271.1 Hrs 4.8 Hrs 1,271.1 Hrs	4,553.8 Hrs	3,278.9 Hrs	
Replace	Drive Bushing	430-010-124-103 A-169	5,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	5,000.0 Hrs	3,725.1 Hrs	
Replace	Bolt	20-065-08083 See HSR	5,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	5,000.0 Hrs	3,725.1 Hrs	
Replace	Actuator Support Assembly	222-040-125-001 A-276	5,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	5,000.0 Hrs	3,725.1 Hrs	
Replace	Pitch Horn to Universal Bolt	50-047C6-36 NSN	5,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	5,000.0 Hrs	3,725.1 Hrs	
Replace	Universal to Pitch Link Bolt	50-047C6-28 NSN	5,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	5,000.0 Hrs	3,725.1 Hrs	
Replace	Pitch Link to Rotating Ring Bolt	50-047C6-32 NSN	5,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	5,000.0 Hrs	3,725.1 Hrs	
Replace	Drive Hub to Drive Hub Bolt	20-057C5-19 NSN	5,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	5,000.0 Hrs	3,725.1 Hrs	
Replace	Drive Hub to Idler Link Bolt	50-047C6-99 NSN	5,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	5,000.0 Hrs	3,725.1 Hrs	

Code Action ATA Eng No	Event Name IRN / Task Number Comment	Identification Part Number / AD Serial Number / Ref	Required Every / in Tolerance	Event On A/C TTIS Event TSO Event TSN	Current Life Since O/H Since Install Since New	Due Airframe TTIS Date	Life Left Hours	Work Package Details
Replace	Idler Link to Drive Link Bolt	50-047C6-99 NSN	5,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	5,000.0 Hrs	3,725.1 Hrs	
Replace	Drive Link to Rotating Ring Bolt	50-047C6-49 NSN	5,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	5,000.0 Hrs	3,725.1 Hrs	
Replace	Non-rotating Ring to Cyclic Link Bolt	50-047C6-32 NSN	5,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	5,000.0 Hrs	3,725.1 Hrs	
Replace	Cyclic Link to Cyclic Lever Bolt	50-047C6-32 NSN	5,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	5,000.0 Hrs	3,725.1 Hrs	
Replace	Cyclic Lever to Actuator Bolt	50-047C8-31 NSN	5,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	5,000.0 Hrs	3,725.1 Hrs	
Replace	Collective Lever to Idler Link Bolt	50-047C8-135 NSN	5,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	5,000.0 Hrs	3,725.1 Hrs	
Replace	Idler Link to Swashplate Support Bolt	50-047C8-82 NSN	5,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	5,000.0 Hrs	3,725.1 Hrs	
Replace	Ball Sleeve to Collective Lever Pin	430-010-442-101 A-201	5,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	5,000.0 Hrs	3,725.1 Hrs	
Replace	Collective Lever to Cyclic Lever Pin	430-010-455-101 ST-91	5,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	5,000.0 Hrs	3,725.1 Hrs	
Replace	Tail Rotor Blade Assembly	222-016-001-139M A-1821	5,000.0 Hrs Mths 0 hrs	1,133.3 Hrs 1,133.3 Hrs 1,133.3 Hrs	1,274.9 Hrs 141.6 Hrs 1,274.9 Hrs	5,000.0 Hrs	3,725.1 Hrs	
Replace	Tail Rotor Yoke Assembly	222-012-702-109 A-421	5,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	5,000.0 Hrs	3,725.1 Hrs	
Replace	Tail Rotor Trunion Assembly	222-012-703-107 A-84	5,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	5,000.0 Hrs	3,725.1 Hrs	

Code	Event	Identification	Required	Event On	Current Life	Due	Life Left
Action	Name	Part Number / AD	Every / in	A/C TTIS	Since O/H	Airframe TTIS	Hours
ATA	IRN / Task Number	Serial Number / Ref	Tolerance	Event TSO	Since Install	Date	
Eng No	Comment			Event TSN	Since New		
Work Package Details							
Replace	Tail Rotor Output Shaft	222-042-402-005 A-382	5,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	5,000.0 Hrs	3,725.1 Hrs
Overhaul	Swashpalte & Support Assembly 5-53	430-010-400-103 49063	5,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	5,000.0 Hrs	3,725.1 Hrs
Overhaul	Tail Rotor Gearbox Assembly 5-53	222-042-001-101 A-706	5,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	5,000.0 Hrs	3,725.1 Hrs
Replace	Tail Rotor Blade Assembly	222-016-001-139M A-1867	5,000.0 Hrs Mths 0 hrs	1,133.3 Hrs 1,133.3 Hrs 1,133.3 Hrs	1,274.9 Hrs 141.6 Hrs 1,274.9 Hrs	5,000.0 Hrs	3,725.1 Hrs
Replace	Ball Sleeve to Collective Lever Pin	430-010-442-101 A-197	5,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	5,000.0 Hrs	3,725.1 Hrs
Replace	Collective Lever to Cyclic Lever Pin	430-010-455-101 ST-102	5,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	5,000.0 Hrs	3,725.1 Hrs
Replace	Drive Bushing	430-010-124-103 A-147	5,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	5,000.0 Hrs	3,725.1 Hrs
Replace	Drive Bushing	430-010-124-103 A-158	5,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	5,000.0 Hrs	3,725.1 Hrs
Replace	Drive Bushing	430-010-124-103 A-159	5,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	5,000.0 Hrs	3,725.1 Hrs
Replace	Drive Bushing	430-010-124-103 A-141	5,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	5,000.0 Hrs	3,725.1 Hrs
Replace	Drive Bushing	430-010-124-103 A-166	5,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	5,000.0 Hrs	3,725.1 Hrs
Replace	Drive Bushing	430-010-124-103 A-148	5,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	5,000.0 Hrs	3,725.1 Hrs

Code Action ATA Eng No	Event Name IRN / Task Number Comment	Identification Part Number / AD Serial Number / Ref	Required Every / in Tolerance	Event On A/C TTIS Event TSO Event TSN	Current Life Since O/H Since Install Since New	Due Airframe TTIS Date	Life Left Hours
Replace	Drive Bushing	430-010-124-103 A-168	5,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	5,000.0 Hrs	3,725.1 Hrs
Overhaul	Main Transmission Assembly 5-53	430-040-003-109 A-71	5,000.0 Hrs Mths 0 hrs	607.9 Hrs 0.0 Hrs 607.9 Hrs	667.0 Hrs 667.0 Hrs 1,274.9 Hrs	5,607.9 Hrs	4,333.0 Hrs
Overhaul	Main Rotor Mast Assembly 5-53	430-110-400-105 A-69	5,000.0 Hrs Mths 0 hrs	607.9 Hrs 0.0 Hrs 607.9 Hrs	667.0 Hrs 667.0 Hrs 1,274.9 Hrs	5,607.9 Hrs	4,333.0 Hrs
Replace	Collective Lever to Actuator Bolt	50-047C8-31 NSN	5,000.0 Hrs Mths 0 hrs	745.3 Hrs 0.0 Hrs 0.0 Hrs	529.6 Hrs 529.6 Hrs 529.6 Hrs	5,745.3 Hrs	4,470.4 Hrs
Replace	LH Actuator to Actuator Support Bolt	50-047C8-31 NSN	5,000.0 Hrs Mths 0 hrs	745.3 Hrs 0.0 Hrs 0.0 Hrs	529.6 Hrs 529.6 Hrs 529.6 Hrs	5,745.3 Hrs	4,470.4 Hrs
Replace	RH Actuator to Actuator Support Bolt	50-047C8-31 NSN	5,000.0 Hrs Mths 0 hrs	745.3 Hrs 0.0 Hrs 0.0 Hrs	529.6 Hrs 529.6 Hrs 529.6 Hrs	5,745.3 Hrs	4,470.4 Hrs
Overhaul	Main Drive Shaft 5-53	222-044-006-111 A488	5,000.0 Hrs 60 Mths 0 hrs	1,272.9 Hrs 0.0 Hrs 1,272.9 Hrs	2.0 Hrs 2.0 Hrs 1,274.9 Hrs	6,272.9 Hrs 28 Mar 2015	4,998.0 Hrs
Overhaul	Main Drive Shaft 5-53	222-044-006-111 A498	5,000.0 Hrs 60 Mths 0 hrs	1,272.9 Hrs 0.0 Hrs 1,272.9 Hrs	2.0 Hrs 2.0 Hrs 1,274.9 Hrs	6,272.9 Hrs 28 Mar 2015	4,998.0 Hrs
Replace	Impeller Assembly 1	23065591 JY101513	7,500.0 Hrs Mths 0 hrs 0 cyc	398.7 Hrs 398.7 Hrs 398.7 Hrs	1,274.9 Hrs 876.2 Hrs 1,274.9 Hrs	7,500.0 Hrs	6,225.1 Hrs
Replace	Impeller Assembly 2	23065591 JY101538	7,500.0 Hrs Mths 0 hrs 0 cyc	398.7 Hrs 398.7 Hrs 398.7 Hrs	1,274.9 Hrs 876.2 Hrs 1,274.9 Hrs	7,500.0 Hrs	6,225.1 Hrs
Replace	Pin Assembly	430-010-127-101 A-0709	10,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	10,000.0 Hrs	8,725.1 Hrs
Replace	Adapter Assembly	430-010-109-101 A-326	10,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	10,000.0 Hrs	8,725.1 Hrs

[Work Package Details](#)

Code Action ATA Eng No	Event Name IRN / Task Number Comment	Identification Part Number / AD Serial Number / Ref	Required Every / in Tolerance	Event On A/C TTIS Event TSO Event TSN	Current Life Since O/H Since Install Since New	Due Airframe TTIS Date	Life Left Hours
Replace	Pitch Horn Assembly	430-010-115-101 A-320	10,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	10,000.0 Hrs	8,725.1 Hrs
Replace	Damper Blade Set	430-310-104-105 LK0399	10,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	10,000.0 Hrs	8,725.1 Hrs
Replace	Shear Restraint	430-310-101-107 LP0396	10,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	10,000.0 Hrs	8,725.1 Hrs
Replace	Clamp Plate Set	430-010-105-105 A-504	10,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	10,000.0 Hrs	8,725.1 Hrs
Replace	Drive Plate Assembly	430-010-126-101 A-90	10,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	10,000.0 Hrs	8,725.1 Hrs
Replace	Main Rotor Pitch Link Assembly	430-010-411-105 TY0289	10,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	10,000.0 Hrs	8,725.1 Hrs
Replace	Main Rotor Pitch Link Assembly	430-010-411-107 TY0280	10,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	10,000.0 Hrs	8,725.1 Hrs
Replace	Drive Hub Assembly	430-010-410-101 RE61	10,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	10,000.0 Hrs	8,725.1 Hrs
Replace	Drive Link Assembly	430-010-408-101 RE79	10,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	10,000.0 Hrs	8,725.1 Hrs
Replace	Rotating Ring Assembly	430-010-401-101 RE73	10,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	10,000.0 Hrs	8,725.1 Hrs
Replace	Non-Rotating Ring Assembly	430-010-402-101 RE79	10,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	10,000.0 Hrs	8,725.1 Hrs
Replace	Cyclic Link Assembly	430-010-412-105 RE236	10,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	10,000.0 Hrs	8,725.1 Hrs

[Work Package Details](#)

Code Action ATA Eng No	Event Name IRN / Task Number Comment	Identification Part Number / AD Serial Number / Ref	Required Every / in Tolerance	Event On A/C TTIS Event TSO Event TSN	Current Life Since O/H Since Install Since New	Due Airframe TTIS Date	Life Left Hours
Replace	Swashplate Support Assembly	430-010-404-101 A-88	10,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	10,000.0 Hrs	8,725.1 Hrs
Replace	Swashplate Ball and Sleeve Assembly	430-010-403-105 A-136	10,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	10,000.0 Hrs	8,725.1 Hrs
Replace	Collective Lever Assembly	430-010-405-105 A-94	10,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	10,000.0 Hrs	8,725.1 Hrs
Replace	Collective Idler Link Assembly	430-010-407-101 RE76	10,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	10,000.0 Hrs	8,725.1 Hrs
Replace	Cyclic Lever Assembly	430-010-406-101 RE154	10,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	10,000.0 Hrs	8,725.1 Hrs
Replace	Main Rotor Mast Assembly	430-040-130-109 A-69	10,000.0 Hrs Mths 0 hrs	607.9 Hrs 607.9 Hrs 607.9 Hrs	1,274.9 Hrs 667.0 Hrs 1,274.9 Hrs	10,000.0 Hrs	8,725.1 Hrs
Replace	Pylon Fluid Mount	430-310-200-107 LK-0132	10,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	10,000.0 Hrs	8,725.1 Hrs
Replace	Pylon Fluid Mount	430-310-200-107 LK-0142	10,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	10,000.0 Hrs	8,725.1 Hrs
Replace	Main Rotor Pitch Link Assembly	430-010-411-105 TY0274	10,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	10,000.0 Hrs	8,725.1 Hrs
Replace	Main Rotor Pitch Link Assembly	430-010-411-107 TY0282	10,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	10,000.0 Hrs	8,725.1 Hrs
Replace	Shear Restraint	430-310-101-107 LP0403	10,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	10,000.0 Hrs	8,725.1 Hrs
Replace	Adapter Assembly	430-010-109-101 A-329	10,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	10,000.0 Hrs	8,725.1 Hrs

[Work Package Details](#)

Code Action ATA Eng No	Event Name IRN / Task Number Comment	Identification Part Number / AD Serial Number / Ref	Required Every / in Tolerance	Event On A/C TTIS Event TSO Event TSN	Current Life Since O/H Since Install Since New	Due Airframe TTIS Date	Life Left Hours	Work Package Details
Replace	Pitch Horn Assembly	430-010-115-101 A-337	10,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	10,000.0 Hrs	8,725.1 Hrs	
Replace	Damper Blade Set	430-310-104-105 LK0415	10,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	10,000.0 Hrs	8,725.1 Hrs	
Replace	Clamp Plate Set	430-010-105-105 A-501	10,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	10,000.0 Hrs	8,725.1 Hrs	
Replace	Pitch Horn Assembly	430-010-115-101 A-331	10,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	10,000.0 Hrs	8,725.1 Hrs	
Replace	Pitch Horn Assembly	430-010-115-101 A-333	10,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	10,000.0 Hrs	8,725.1 Hrs	
Replace	Damper Blade Set	430-310-104-105 LK0391	10,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	10,000.0 Hrs	8,725.1 Hrs	
Replace	Damper Blade Set	430-310-104-105 LK0411	10,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	10,000.0 Hrs	8,725.1 Hrs	
Replace	Adapter Assembly	430-010-109-101 A-321	10,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	10,000.0 Hrs	8,725.1 Hrs	
Replace	Adapter Assembly	430-010-109-101 A-325	10,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	10,000.0 Hrs	8,725.1 Hrs	
Replace	Shear Restraint	430-310-101-107 LP0417	10,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	10,000.0 Hrs	8,725.1 Hrs	
Replace	Shear Restraint	430-310-101-107 LP0418	10,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	10,000.0 Hrs	8,725.1 Hrs	
Replace	Cyclic Link Assembly	430-010-412-105 RE248	10,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	10,000.0 Hrs	8,725.1 Hrs	

Code Action ATA Eng No	Event Name IRN / Task Number Comment	Identification Part Number / AD Serial Number / Ref	Required Every / in Tolerance	Event On A/C TTIS Event TSO Event TSN	Current Life Since O/H Since Install Since New	Due Airframe TTIS Date	Life Left Hours
Replace	Pin Assembly	430-010-127-101 A-0742	10,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	10,000.0 Hrs	8,725.1 Hrs
Replace	Pin Assembly	430-010-127-101 A-0720	10,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	10,000.0 Hrs	8,725.1 Hrs
Replace	Pin Assembly	430-010-127-101 A-0732	10,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	10,000.0 Hrs	8,725.1 Hrs
Replace	Pin Assembly	430-010-127-101 A-0708	10,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	10,000.0 Hrs	8,725.1 Hrs
Replace	Pin Assembly	430-010-127-101 A-0721	10,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	10,000.0 Hrs	8,725.1 Hrs
Replace	Pin Assembly	430-010-127-101 A-0726	10,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	10,000.0 Hrs	8,725.1 Hrs
Replace	Pin Assembly	430-010-127-101 A-0756	10,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	10,000.0 Hrs	8,725.1 Hrs
Replace	Clamp Plate Set	430-010-105-105 A-490	10,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	10,000.0 Hrs	8,725.1 Hrs
Replace	Clamp Plate Set	430-010-105-105 A-507	10,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	10,000.0 Hrs	8,725.1 Hrs
Replace	Clamp Plate Set	430-010-105-105 A-507	10,000.0 Hrs Mths 0 hrs	0.0 Hrs 0.0 Hrs 0.0 Hrs	1,274.9 Hrs 1,274.9 Hrs 1,274.9 Hrs	10,000.0 Hrs	8,725.1 Hrs
Replace	Drive Idler Link Assembly	430-010-409-105 RE178	10,000.0 Hrs Mths 0 hrs	874.6 Hrs 0.0 Hrs 0.0 Hrs	400.3 Hrs 400.3 Hrs 400.3 Hrs	10,874.6 Hrs	9,599.7 Hrs
Replace	Drive Idler Link Assembly	430-010-409-105 RE90	10,000.0 Hrs Mths 0 hrs	874.6 Hrs 0.0 Hrs 0.0 Hrs	400.3 Hrs 400.3 Hrs 400.3 Hrs	10,874.6 Hrs	9,599.7 Hrs

[Work Package Details](#)

AVTRAC
MAINTENANCE TRACKING

DEVEREAUX HOLDINGS PTY LTD T/A GRIFFIN HELICOPTERS

Aircraft Rego VH - VGG **TTIS on Aircraft** 1,274.9 Updated 28 Jul 2011

Cycles 2,000 Updated 28 Jul 2011

Due List Status

CURRENT

Report Date

28 Jul 2011

Report Type 050

- Time Lfied Items
- Date Lfied Items
- Cycle Lfied Items
- Ldg Lfied Items

Aircraft Serial No 49063

Aircraft Model No 430

Code	Event	Identification	Required	Event On	Current Life	Due	Life Left
Action	Name	Part Number / AD	Every / in	A/C TTIS	Since O/H	Airframe TTIS	Hours
ATA	IRN / Task Number	Serial Number / Ref	Tolerance	Event TSO	Since Install	Date	
Eng No	Comment			Event TSN	Since New		

[Work Package Details](#)

End of Report

Aircraft Serial No 49063

Aircraft Model No 430

Code Action ATA Eng No	Event Name IRN / Task Number Comment	Identification Part Number / AD Serial Number / Ref	Required Every / in Tolerance	Installed Date	Due Date	Life Left Hours	Work Package Details
Inspect 0500	Main Driveshaft 5-31	Bell 430 MM Griffin Helicopters SOM	600.0 Hrs 12 Mths +/- 60 hrs 1 mth	3 May 2010	2 May 2011	-2 Mths	Work in Progress
Inspect 0500	Tail Rotor Driveshaft 5-31	Bell 430 MM Griffin Helicopters SOM	600.0 Hrs 12 Mths +/- 60 hrs 1 mth	3 May 2010	2 May 2011	-2 Mths	Work in Progress
Test 0500	Standby Attitude Indicator 5-35	Bell 430 MM Griffin Helicopters SOM	Hrs 6 Mths +/- 15 days	1 Dec 2010	1 Jun 2011	-1 Mths	Work in Progress
Check	Cockpit Fire Extinguisher	AD/FPE/6 amd 7 Reweigh	Hrs 6 Mths 0 mths	1 Dec 2010	1 Jun 2011	-1 Mths	Work in Progress
Check	Cabin Fire Extinguisher	AD/FPE/6 amd 7 Reweigh	Hrs 6 Mths 0 mths	1 Dec 2010	1 Jun 2011	-1 Mths	Work in Progress
Change	Tail Rotor Gearbox 12-1	Oil Change BHT-430-MM-2	150.0 Hrs 6 Mths +/- 15 hrs 15 days	1 Dec 2010	1 Jun 2011	-1 Mths	Work in Progress
Inspect 0500	Eng Fire Ext & Cartridge 5-30	Bell 430 MM Griffin Helicopters SOM	600.0 Hrs 6 Mths +/- 60 hrs 15 days	1 Dec 2010	1 Jun 2011	-1 Mths	Work in Progress
Service 1	Engine Oil 12-1	BHT-430-MM-2	600.0 Hrs 6 Mths +/- 30 hrs 15 days	1 Dec 2010	1 Jun 2011	-1 Mths	Work in Progress
Service 2	Engine Oil 12-1	BHT-430-MM-2	600.0 Hrs 6 Mths +/- 30 hrs 15 days	1 Dec 2010	1 Jun 2011	-1 Mths	Work in Progress
Service	Nose Landing Gear 12-1	Centering Actuator BHT-430-MM-2	600.0 Hrs 6 Mths +/- 30 hrs 15 days	1 Dec 2010	1 Jun 2011	-1 Mths	Work in Progress
Lubricate	300 Hr/12 Mth Lubrication 12-5	MLG & NLG Wheels BHT-430-MM-2	300.0 Hrs 12 Mths +/- 30 hrs 1 mth	3 Jun 2010	2 Jun 2011	-1 Mths	Work in Progress
Inspect 0500	600 Hourly Inspection 5-15	Bell 430 MM Griffin Helicopters SOM	600.0 Hrs 12 Mths +/- 60 hrs 1 mth	3 Jun 2010	2 Jun 2011	-1 Mths	Work in Progress

Aircraft Serial No 49063

Aircraft Model No 430

Code Action ATA Eng No	Event Name IRN / Task Number Comment	Identification Part Number / AD Serial Number / Ref	Required Every / in Tolerance	Installed Date	Due Date	Life Left Hours	Work Package Details
Change	Transmission 12-1	Oil Change BHT-430-MM-2	600.0 Hrs 12 Mths +/- 60 hrs 1 mth	3 Jun 2010	2 Jun 2011	-1 Mths	Work in Progress
Change	Hydraulic Reservoir 12-1	Oil Change BHT-430-MM-2	600.0 Hrs 12 Mths +/- 60 hrs 1 mth	3 Jun 2010	2 Jun 2011	-1 Mths	Work in Progress
Lubricate	600 Hr / 12 Mth Lubrication 12-5	Driveshafts BHT-430-MM-2	600.0 Hrs 12 Mths +/- 60 hrs 1 mth	3 Jun 2010	2 Jun 2011	-1 Mths	Work in Progress
Action	Reweigh		Hrs 36 Mths + Next periodic	11 Sep 2008	4 Jun 2011	-1 Mths	Work in Progress
Action	Battery 12-1	Deep Cycle BHT-430-MM-2	Hrs 3 Mths +/- 1 mth	29 Apr 2011	28 Jul 2011	0 Mths	Work in Progress
Inspect 0500	50 Hourly Inspection 5-13	Bell 430 MM Griffin Helicopters SOM	50.0 Hrs 12 Mths +/- 5 hrs 1 mth	23 Aug 2010	22 Aug 2011	1 Mths	Work in Progress
Inspect 0500	Directional Flight Control Bearing 5-14	ASB 430-10-45 REV A	150.0 Hrs 12 Mths +/- 15 hrs 1 mth	23 Aug 2010	22 Aug 2011	1 Mths	Work in Progress
Inspect 0500	IFR Radio Periodic	Pages 12 & 13 Griffin Helicopters SOM	300.0 Hrs 12 Mths 0 hrs 0 mths	23 Aug 2010	22 Aug 2011	1 Mths	Work in Progress
Overhaul	Cyclic Servo	ASB-430-10-44 HR-460A	1,200.0 Hrs 12 Mths 0 hrs 0 mths	23 Aug 2010	22 Aug 2011	1 Mths	Work in Progress
Overhaul	Cyclic Servo	ASB-430-10-44 HR-461A	1,200.0 Hrs 12 Mths 0 hrs 0 mths	23 Aug 2010	22 Aug 2011	1 Mths	Work in Progress
Overhaul	Cyclic Servo	ASB-430-10-44 HR-462A	1,200.0 Hrs 12 Mths 0 hrs 0 mths	23 Aug 2010	22 Aug 2011	1 Mths	Work in Progress
Inspect 0500	Swashplate and Controls 5-36	Bell 430 MM Griffin Helicopters SOM	Hrs 24 Mths +/- 1 mth	28 Sep 2009	27 Sep 2011	2 Mths	

<u>Code</u> Action ATA Eng No	<u>Event</u> Name IRN / Task Number Comment	<u>Identification</u> Part Number / AD Serial Number / Ref	<u>Required</u> Every / in Tolerance	<u>Installed</u> Date	<u>Due</u> Date	<u>Life Left</u> Hours
Inspect 0500	Main Rotor Mast 5-36	Bell 430 MM Griffin Helicopters SOM	Hrs 24 Mths +/- 1 mth	28 Sep 2009	27 Sep 2011	2 Mths
Action 0500	Intruments 5-36	Bell 430 MM Griffin Helicopters SOM	Hrs 24 Mths +/- 1 mth	28 Sep 2009	27 Sep 2011	2 Mths
Inspect 0500	Vertical Fin 5-36	Bell 430 MM Griffin Helicopters SOM	Hrs 24 Mths +/- 1 mth	28 Sep 2009	27 Sep 2011	2 Mths
Action 0500	System of Maintenance	Review 12 month	Hrs 12 Mths + 1 mth	1 Dec 2010	1 Dec 2011	5 Mths
Test	Transponder	AD/RAD/47 amd 2	Hrs 24 Mths 0 mths	23 Aug 2010	10 Jan 2012	6 Mths
Calibrate	Compass Swing	No 1, Standby, No 2 CAO 108.6 Issue 2	Hrs 36 Mths 0 mths	17 Feb 2009	16 Feb 2012	7 Mths
Inspect	Corrosion Inspection	Bell 430 MM	100.0 Hrs 3 Mths +/- 10 rs 3 days	29 Apr 2011	28 Apr 2012	9 Mths
Inspect 0500	150 Hourly Inspection 5-14	Bell 430 MM Griffin Helicopters SOM	150.0 Hrs 12 Mths +/- 15 hrs 1 mth	29 Apr 2011	28 Apr 2012	9 Mths
Replace 0500	Maintenance Release	CASA 918 S/N A72393	165.0 Hrs 13 Mths 0 hrs 0 mths	29 Apr 2011	28 May 2012	10 Mths
Test	Instruments	AD/INST/9 amd 6 2 years option	Hrs 24 Mths 0 mths	23 Aug 2010	22 Aug 2012	13 Mths
Test	Transponder	AD/RAD/43 and 6	Hrs 24 Mths 0 mths	23 Aug 2010	22 Aug 2012	13 Mths
Overhaul	Hangar Assembly 5-53	222-044-003-113 BP-449	3,000.0 Hrs 36 Mths 0 hrs	23 Nov 2009	22 Nov 2012	16 Mths

[Work Package Details](#)

Aircraft Serial No 49063

Aircraft Model No 430

<u>Code</u> Action ATA Eng No	<u>Event</u> Name IRN / Task Number Comment	<u>Identification</u> Part Number / AD Serial Number / Ref	<u>Required</u> Every / in Tolerance	<u>Installed</u> Date	<u>Due</u> Date	<u>Life Left</u> Hours
Overhaul	Hangar Assembly 5-53	222-044-003-113 BP-448	3,000.0 Hrs 36 Mths 0 hrs	23 Nov 2009	22 Nov 2012	16 Mths
Overhaul	Hangar Assembly 5-53	222-044-003-115 49063	3,000.0 Hrs 36 Mths 0 hrs	23 Nov 2009	22 Nov 2012	16 Mths
Replace	Cockpit Fire Extinguisher	AD/FPE/6 amd 7 Retirement Life	Hrs 144 Mths 0 mths	31 Dec 2000	30 Dec 2012	17 Mths
Replace	Attitude Indicator AWAITING CASA INSTRUMENT	CASA Inst WOP 9272 Refer to Instrument in Log Books	Hrs 24 Mths 0 mths	1 Dec 2010	31 Dec 2012	17 Mths
Replace	No 1 RH Cartridge Fire Extinguisher	13083-5 10-06	Hrs 72 Mths 0 mths	22 Aug 2007	21 Aug 2013	25 Mths
Replace	No 2 RH Cartridge Fire Extinguisher	13083-5 10-06	Hrs 72 Mths 0 mths	22 Aug 2007	21 Aug 2013	25 Mths
Test 0500	Fire Ext Reservoir 5-38	Bell 430 MM Griffin Helicopters SOM	Hrs 60 Mths +/- 1 mth	23 Nov 2009	22 Nov 2014	40 Mths
Test	LH Fire Extinguisher	222-369-911-001 36312A1	Hrs 60 Mths 0 mths	23 Nov 2009	22 Nov 2014	40 Mths
Test	RH Fire Extinguisher	222-369-911-001 36311A1	Hrs 60 Mths 0 mths	23 Nov 2009	22 Nov 2014	40 Mths
Replace 3400	ELT Battery	P/N 453-0422-269 S/N 906	Hrs 60 Mths 0 mths	30 Nov 2009	30 Nov 2014	40 Mths
Replace	Float Reservoir	222-325-021-101	Hrs 180 Mths 0 mths	15 Feb 2000	14 Feb 2015	43 Mths
Replace	Float Reservoir	222-025-875-101	Hrs 180 Mths 0 mths	15 Feb 2000	14 Feb 2015	43 Mths

[Work Package Details](#)

Aircraft Serial No 49063

Aircraft Model No 430

<u>Code</u> Action ATA Eng No	<u>Event</u> Name IRN / Task Number Comment	<u>Identification</u> Part Number / AD Serial Number / Ref	<u>Required</u> Every / in Tolerance	<u>Installed</u> Date	<u>Due</u> Date	<u>Life Left</u> Hours
Overhaul	Main Drive Shaft 5-53	222-044-006-111 A488	5,000.0 Hrs 60 Mths 0 hrs	29 Mar 2010	28 Mar 2015	44 Mths
Overhaul	Main Drive Shaft 5-53	222-044-006-111 A498	5,000.0 Hrs 60 Mths 0 hrs	29 Mar 2010	28 Mar 2015	44 Mths
Replace	No 1 LH Cartridge Fire Extinguisher	13083-5 NSN	Hrs 72 Mths 0 mths	23 Nov 2009	22 Nov 2015	52 Mths
Replace	No 2 LH Cartridge Fire Extinguisher	13083-5 NSN	Hrs 72 Mths 0 mths	23 Nov 2009	22 Nov 2015	52 Mths
Replace	Cabin Fire Extinguisher	AD/FPE/6 amd 7 Retirement Life	Hrs 144 Mths 0 mths	7 Oct 2009	6 Oct 2021	123 Mths

[Work Package Details](#)

End of Report

Aircraft Serial No 49063

Aircraft Model No 430

Code Action ATA Eng No	Event Name IRN / Task Number Comment	Identification Part Number / AD Serial Number / Ref	Required Every / in Tolerance	Event On A/C Cyc Event CSO Event CSN	Current Life Since O/H Since Install Since New	Due		Life Left Hours
						Airframe Cyc Date	Work Package Details	
Replace 1	First Stage Wheel	23053299 X146181	3,000 Cyc Mths 0 hrs 0 cyc	779 Cyc 2,000 Cyc 779 Cyc	2,000Cyc 1,221 Cyc 2,000 Cyc	3,000Cyc		1,000 Cyc
Replace 1	Second Stage Wheel	23032280 HX128367	3,000 Cyc Mths 0 hrs 0 cyc	779 Cyc 2,000 Cyc 779 Cyc	2,000Cyc 1,221 Cyc 2,000 Cyc	3,000Cyc		1,000 Cyc
Replace 2	Second Stage Wheel	23032280 HX128595	3,000 Cyc Mths 0 hrs 0 cyc	1,992 Cyc 1,993 Cyc 1,985 Cyc	1,993Cyc 8Cyc 1,993 Cyc	3,007Cyc		1,007 Cyc
Replace 2	First Stage Wheel	23053299 X575880	3,000 Cyc Mths 0 hrs 0 cyc	1,992 Cyc 8 Cyc 0 Cyc	8Cyc 8Cyc 8Cyc	4,992Cyc		2,992 Cyc
Replace 1	Third Stage Wheel	6898663 HX93090	6,000 Cyc Mths 0 hrs 0 cyc	779 Cyc 2,000 Cyc 779 Cyc	2,000Cyc 1,221 Cyc 2,000 Cyc	6,000Cyc		4,000 Cyc
Replace 1	Fourth Stage Wheel	23066744 HX75032	6,000 Cyc Mths 0 hrs 0 cyc	779 Cyc 2,000 Cyc 779 Cyc	2,000Cyc 1,221 Cyc 2,000 Cyc	6,000Cyc		4,000 Cyc
Replace 2	Third Stage Wheel	6898663 HX93158	6,000 Cyc Mths 0 hrs 0 cyc	1,992 Cyc 1,993 Cyc 1,985 Cyc	1,993Cyc 8Cyc 1,993 Cyc	6,007Cyc		4,007 Cyc
Replace 2	Fourth Stage Wheel	23066744 HX75021	6,000 Cyc Mths 0 hrs 0 cyc	1,992 Cyc 1,993 Cyc 1,985 Cyc	1,993Cyc 8Cyc 1,993 Cyc	6,007Cyc		4,007 Cyc
Replace 1	Impeller Assembly	23065591 JY101513	15,000 Cyc Mths 0 hrs 0 cyc	779 Cyc 2,000 Cyc 779 Cyc	2,000Cyc 1,221 Cyc 2,000 Cyc	15,000Cyc		13,000 Cyc
Replace 2	Impeller Assembly	23065591 JY101538	15,000 Cyc Mths 0 hrs 0 cyc	777 Cyc 2,000 Cyc 777 Cyc	2,000Cyc 1,223 Cyc 2,000 Cyc	15,000Cyc		13,000 Cyc

End of Report