

Vintage Piano Workshop

1808 Conita Real SW
Albuquerque NM 87105

255-0658

date

April 14, 2014

Rebuilding Estimate

Steinway

make

B

model

serial no.

Zorro Ranch
name
49 Zorro Ranch Rd.
address
Stanley, NM 87056
city zip
505-832-2675
phone

parts labor

| | | |
|---|---|--------|
| restringing | 6 hours to replace broken tuning pins (100.00/hr) | 600.00 |
| new pin block | | |
| soundboard: rib regluing | | |
| crack shimming | | |
| refinishing | | |
| bridges: regluing pins | | |
| new bass bridge or cap | | |
| new treble cap | | |
| plate: refinishing | | |
| relettering | | |
| dampers: new felt | | |
| rebush guide rails | | |
| install set-screw sockets | | |
| action: keys: rebush front | as needed | 200.00 |
| rebush balance | as needed | 200.00 |
| recover whites | | |
| recover whites w/ fronts | | |
| recover sharps (plastic) | | |
| recover backchecks | | |
| replace key end felt | | |
| replace keyframe punchings | | |
| replace backrail cloth | | |
| regulating | | |
| new hammers | | |
| new hammer shanks | | |
| recondition original hammers (check travel, bolster knuckles, repin, reshape, space, tighten) | | 400.00 |
| reshape orig. hammer tails | | |
| new knuckles | | |

parts labor

recondition wippens (clean springs,
center jacks, repin, replace felt,
space, tighten)

legs & lyre: repairs to wood
repair/replace hardware
clean, buff & lacquer brass
replace felt, leather, etc.

refinishing: piano
bench
hardware

other:

round trip moving: 2 Trip charges @ 100.00 ea.
turning

200.00
250.00

Estimate prices are guaranteed for 6 months
or until the job can be begun. Your satis-
faction with my work will be guaranteed for
2 years, parts and labor.

| | |
|----------|----------------|
| parts | |
| labor | <u>1850.00</u> |
| subtotal | <u>1850.00</u> |
| NM tax | <u>112.16</u> |
| total | <u>1962.16</u> |

Thank you,

Leroy and Lee Conner

Once the piano action is disassembled in the shop there
are frequently additional repairs that need to be made. Therefore
the estimate cost may be as much as 20% higher to compensate
for any unforeseen repairs. If anything major is found the
owner will be notified before any additional work is begun.