

From: Richard Kahn <[REDACTED]>
To: Jeffrey Epstein <jeevacation@gmail.com>
Subject: Buck Steel
Date: Tue, 25 Sep 2012 14:33:32 +0000
Attachments: SKMBT_C25312092510080.pdf

after speaking with Buck Steel yesterday and as you suspected the middle section of the 60' side cannot have doors as they have hurricane bracings
is diagram below with red markings ok to proceed with
please advise

Richard Kahn
HBRK Associates Inc.
575 Lexington Avenue, 4th Floor,
New York, New York 10022

Begin forwarded message:

From: [REDACTED]
Date: September 25, 2012 10:09:04 AM EDT
To: [REDACTED]
Subject: Message from KMBT_C253
Reply-To: [REDACTED]