

From: Richard Kahn <[REDACTED]>

To: "jeffrey E." <jeevacation@gmail.com>

Subject: Fwd: ZDC-HWS Repair

Date: Fri, 19 Sep 2014 14:43:13 +0000

Attachments: ZDC-HWS_Bids.pdf

Inline-Images: HWS_Pipes.JPG; HWS_1.JPG; HWS_2.JPG; HWS_3.JPG; Ind_Leak.JPG;
Stone_Band.JPG

Richard Kahn
HBRK Associates Inc.



Begin forwarded message:

From: Brice Gordon <[REDACTED]>

Subject: Fwd: ZDC-HWS Repair

Date: September 15, 2014 at 1:00:16 PM EDT

To: Rich Kahn <[REDACTED]>

Cc: Zorro Ranch <[REDACTED]>

Rich

sorry the bids did not attach to original e mail, have re scanned and attached for your information.
please let me know when we can review

Brice

----- Forwarded message -----

From: Brice Gordon <[REDACTED]>

Date: Fri, Sep 12, 2014 at 11:51 AM

Subject: ZDC-HWS Repair

To: Rich Kahn <[REDACTED]>

Cc: Zorro Ranch <[REDACTED]>

Rich

Attached are:

Photos of HWS (Hot Supply Pipes), location of leak, example of Stone Band.
E mail Dated Jun 19th to John and yourself regarding leak.

Estimates from 3 B's (\$11,700) and P&M Construction (\$11,800)

HWS pipes supply hot water from the boiler in the Mechanical Room to the auxiliary heating coils and radiant floor heat in the Main House

The attached estimates are to cut, remove existing concrete pad and expose pipes to determine repair.

Once leak/damage has been found estimates will be sort to fix leak.

How do you wish to proceed.

Brice Gordon

[REDACTED]

Ph: [REDACTED]

--

Brice Gordon

[REDACTED]

Ph: [REDACTED]



