

Forward Salon**Cabin Seats:****L/H # 1 Aft Facing Seat:**

Recline cylinders have excessive play and need to be replaced. (2- P.L. Porter Hydrolock P/N SLO2300-28)

Seat does not lock into place: Tracking Lever Cable on lower brake clutch area is frayed and needs to be replaced, and brake assembly adjusted. Wire Cable P/N 302303-6-48 and Swage P/N 401-4

Front area on base shroud aluminum bracket is torn out of place and needs to be repaired.

Labor: 4 hrs.

Parts: 2 – P.L. Porter Hydrolocks - SLO2300=28

L/H # 2 Fwd. facing Seat:

Recline cylinder has excessive play and needs to be replaced. (1- P.L. Porter Hydrolock P/N SLO2300-28)

Seat does not lock into place: Tracking Lever Cable on lower brake clutch area is frayed and needs to be replaced, and brake assembly adjusted. Wire Cable (302303-6-48)

Front area on base shroud aluminum bracket is torn out of place and needs to be repaired.

Labor: 2 hr.

Parts: 1 – P.L. Porter Hydrolocks - SLO2300=28

R/H #1 Inboard fwd. facing seat:

Recline cylinder has excessive play and needs to be replaced. (1- P.L. Porter Hydrolock P/N SLO2300-28)

Labor: 1 hr.

Parts: 1 – P.L. Porter Hydrolocks - SLO2300=28

R/H #1 Outboard fwd. facing seat:

Recline cylinder has excessive play and needs to be replaced. (1- P.L. Porter Hydrolock P/N SLO2300-28)

Labor: 1 hr.

Parts: 1 – P.L. Porter Hydrolocks - SLO2300=28

Aft. Facing Triple Seat:

Recline cylinder has excessive play and needs to be replaced. (1- P.L. Porter Hydrolock P/N SLO2300-28)

Labor: 2 hr.

Parts: 3 – P.L. Porter Hydrolocks - SLO2300=21

Fwd. Facing Triple Seat:

Recline cylinder has excessive play and needs to be replaced. (1- P.L. Porter Hydrolock P/N SLO2300-28)

Inboard tracking lever cable is broken and needs to be replaced.

Labor: 3 hr.

Parts: 3 – P.L. Porter Hydrolocks - SLO2300=21

TOTAL:

Labor: 13 hrs.

Parts Cost: 11 – Hydrolocks \$195.00 each cost X 11 = \$3,245.00

Parts Cost: 2 – P/N 302303-6-48 & swage P/N 401-4 \$35.00

Shipping: _____?