

Reefco Services, Inc.



Invoice

Date	Invoice #
12/3/2018	113814

Bill To
Little Saint James Daphne Wallace

Ship To

Number	Terms	Rep	Ship	Via	F.O.B.	Project
LSJ	Due on receipt	RPQ	12/3/2018			

Quantity	Item Code	Description	U/M	Price Each	Amount
40	C-12	Ft. Communication Line, 4-Wire		2.125	85.00
12	2001	Labor Air-Conditioning and Refrigeration		105.00	1,260.00
1	C-12	BOARD, MAIN PCB		895.00	895.00
1	C-12	FILTER, SPEED CONTROL		635.00	635.00
<p>MANAGER'S BEDROOM: Unit keeps blowing fuse. Traced all wiring, found wiring under house where something has chewed through wire, shorting it. Ran new wire from outdoor unit to indoor unit. All wire repaired. Unit also needs two boards as they were blown. Ordered and replaced board. Unit working well now.</p> <p><i>A/C Repairs - LSS Staff cottage (before transition of management) Replace wiring and two boards.</i></p> <p><i>A/C working. Repairs complete.</i></p> <p><i>Note 12 hrs/labor @ \$105/hr</i></p> <p style="text-align: right;"><i>60155e</i></p>					

Phone #	Fax #	E-mail	Total	\$2,875.00

REEFCO

113814

SERVICES, INC

Marine Refrigeration & Air Conditioning
Reverse Osmosis Desalination Systems

E: [REDACTED]

NAME/VESSEL LSJ		DEPT. 01	DATE 12-3-18
CONTACT/PHONE # "BRICE"		LOCATION MANAGERS BED ROOM	
BRAND NAME FUJITSU	MODEL # AOU24RLB	SERIAL # FRAD15519	
TECH ROD Q	PAYMENT TYPE	AUTH. #	
QUAN.	DESCRIPTION	UNIT PRICE	AMOUNT
	UNIT KEEPS BLOWING FUSE, TRACED ALL WIRING, FOUND WIRING UNDER HOUSE WERE SOMETHING CHOMED THROUGH WIRE AND SHORTED UNIT OUT. RAN NEW WIRE FROM OUTDOOR UNIT TO INDOOR UNIT, WIRE ALL REPAIRED, UNIT ALSO NEEDS TWO BOARDS AS THEY TOO ARE BLOWN, ORDER AND REPAIRED BOARDS, UNIT WORKING WELL NOW.		
40'	4 WIRE COMMUNICATION WIRE	85.00	
12	HRS LABOR	105.00	1260.00
1	MAIN PCB BOARD		895.00
1	STEAD SPREAD CONTROL FILTER		637.00
	TOTAL		24875.00

SIGNATURE

EMAIL

WE APPRECIATE YOUR BUSINESS

