

A/C Actual Compliance Last - Reason

Print Date 2002/2008 11:09
Page: 1 of 36

A/C: A6DFR Type/Serial: B737/RG A/C SN: 30884 A/C Hours: 1294.57 A/C Cycles: 687 As Of: 13/02/2008

E/C (Category: AD)	Document/SB	E/C Description	Schedule Hrs/Cys/Dys/Dte	Remaining/ Next Due	Last Compliance Information
E/C: 1974-08-09 Category: AD Status: OPEN Rev: 9	25-120-00-01 25-130-00-01 25400-60029 254000-DVI-10000-1 254012-0080 254100-01000 74-08-09R2 A122540	WASTE RECEPTACLE DOOR INSPECTION	1000 Hrs	935.28 01/09/2009 Recur EARLIEST	WO 12017 14/01/2008 Rev: 8 A/C Total Hours: 1230.25 A/C Total Cycles: 651 C/OUT DURING 1A CHK. REF TWO 12017
E/C: 1987-08-09 Category: AD Status: TERMINATED Rev: 2	320000 00080	INFLATION OF TIRES WITH NITROGEN			Reason COVERED BY DAILY CHECK TASK. Amount NO 16-01-01 AT WORK STEP 4, 32-00-01-00 Manual Compliance 01/06/1987 Rev: 2 A/C Total Hours: 0.00 A/C Total Cycles: 0 THIS TASK IS CONTROLLED THROUGH DAILY CHECK REF DAILY CHECK TASK CARD.
E/C: 1989-18-12 Category: AD Status: CANCEL Rev: 2	1991-10-02	CLASS B MAIN DECK CARGO COMPARTMENT			Amount NO 39-6557
E/C: 1991-10-02 Category: AD Status: CANCEL Rev: 2	1989-18-12	CLASS B MAIN DECK CARGO COMPARTMENT		Superseded By: 1991-10-02 EARLIEST	Amount NO 39-6986
E/C: 1993-07-15 Category: AD Status: N/A Rev: 2	1989-18-12 1991-10-02	CLASS B MAIN DECK CARGO COMPARTMENT			Amount NO 39-6547

Certified that the above modifications have been embodied by the aircraft constructor at the time of certification of the aircraft, additional to the basic design.

Signed (for Constructor)

Date

MANDATORY MODIFICATION RECORD

Aircraft Registration A6-DFR

Owner's Name AMIRI FLIGHT

Mod Ref. No.	Description of Mod	Mod Approval Reference	Reference to other Modifications Affected	Person Certifying Authority, Signature and Date
2	3	4	5	6
AD 2008-03-01	TRF WITH TANGENTIAL STRUTS - MANDATORY INSPECTIONS - LIFE TIMES.	SB CFM 56-76-72-0579.		AD REQUIREMENT CONTROLLED BY SB CFM 56-76-72-0579. 16/2 TR
AD 2008-05-05	STRUCTURE ATTACHMENT FITTINGS - INADGATE SEALING (BROWND) VERTICAL FIN LUGS.	SB 737-737-53A1242		SB C/OUT 28/05/07 BY BIEINK BARRERL TO CLOSED. AF 12 TR
AD 2008-08-22	GRAY WATER COMPOSITE DRAW MAST BONDING JUMPER INSTALLATION.	SB 737-30-1056	EO 83-30-1056.	SB C/W UNDER TUG 12175 D/H 8/11/08. AF 12 TR
AD 2008-09-14	EMER. FUEL FEED SYS. BOOST PUMP UNTIL RELAY GRD. LOC. CHANGE.	SB 737-28-1257	LHT EO 155 809.	SB C/W BY LHT ON 11/01/07. Ref DEL 82L. AF 12 TR
AD 2008-06-27	EMERG. EVAC. EQUIP. SLIDE RAFTS - SHEAR PIN RESTRAINTS REPLACEMENT.	VISB 25-343		VISB 25-343 C/W ON ALL S/RAFTS. AF 12 TR
AD 2008-06-03	EMER. FUEL FEED SYS. MOTOR OPERATED VLV. ACT. REL. & EMER. FUEL FEED SYS. MOTOR OPERATED VLV. AWL (SB 737-28A1207) C/W & RECD AWLs NOW INCORPORATED TO AMIS.	SB 737-28A1207.		SB C/OUT & RECD AWLs ARE INCORPORATED INTO AMIS. AD CLOSED. AF 12 TR
AD 2008-10-10	AMIS REVISION TO INCLUDE AWL RELATED TO FUEL TANK SYSTEMS.			AWLs ARE INCORPORATED INTO AMIS AS PER AD PER. AD CLOSED. AF 12 TR
AD 2008-11-08	FLIGHT DECK NO. 2, 4 AND 5 WINDOWS INSPECTION.	SB 737-56A1022 (INSP)		
AD 2004-05-19	MODIFICATION OF THE DR'S BOLTS THAT ATTACH THE HORIZONTAL STAB.	SB 737-55-1086		SB C/OUT DURING 2C CHK REF W/O 12142 D/H 08/11/06. AF 12 TR
AD 2005-23-16	CNT. WIRE BUNDLE INSTALLATION CHANNEL.	SB 737-28-1209		SB 28-1209 C/OUT DURING 2C CHK REF W/O 12142 D/H 08/07/08. AF 12 TR
AD 2006-21-01	LUBRICATION & FREELAY CHECK OF AIRCRAFT BALANCE TAB BEARINGS.	SB 737-27-1273		
EASA AD 2006-0440-E	AIR CONDITIONING - ZONAL DRYING SYSTEM DEACTIVATION - EMER. AD.	AD	SNCB73-21-015	REF W/O 12893 D/H 09 OCT. 08. AF 12 TR
AD 2006-07-04	FLUID ACCUMULATION IN ENGINE STRUT AFT FAIRING.	SB 737-54-1041	EO 83-54-1041	MOD PART OF SB C/W REF W/O 16115 019 20/09/11. AF 12 TR

MANDATORY MODIFICATION RECORD

Aircraft Registration A6-DFR
 Owner's Name AMIRI FCJ

Mod Ref. No.	Description of Mod	Mod Approval Reference	Reference to other Modifications Affected	Person Certifying Authority, Signature and Date
AD 2008-22-01	PREVENT USAGE OF AUXILIARY FUEL TANKS - FAA NOTIFICATION 1087 LW BY OA ON 02/11/08.			4007 REF W/O 12640 Dtd 16-08-08.
AD 2008-24-08	EMERGENCY ESCAPE DOOR MOUNTED ESCAPE SYS CHARGE EVACUATION SLIDE INFLATION VALVE REGULATOR.	SB 737-26-1491		PIH SA3307-5 FITTED ON ALL SATISFIES AD REQUIREMENT AD CLOSED.
AD 2008-24-07	EMERGENCY AD - INSPECTION FOR MS-WIRING AFTER ACCOMPLISHMENT OF SB 737-28A1206.			4007 REF W/O 13014 Dtd 19-11-08.
AD 2008-23-07	AIRPLANE FLIGHT MANUAL REVISION - CABIN ALTITUDE WARNING.	EO B3-2008-2307		4007 REF W/O 12982 Dtd 03 DEC. 08.
AD 2008-24-05	WINDSHIELD WIPER MOTOR REPLACEMENT.	SB 737-30A1057		REF W/O 12229 Dtd 11-01-09.
AD 2005-18-23	CORROSION PROTECTION OF ELECTRICAL CONNECTORS IN THE MAIN WHEEL WELL (INSIP CONTROLLED BY EO B3-24A1148)	SB 737-24A1148	EO B3-24A1148.	OPEN
AD 2008-16-13	FLT. CONTROLS - ELEVATOR AND TABS - LEFT & RIGHT ELEVATOR TAB PUSHERS REPLACEMENT.	SB 737-27-1284	EO B3-27-1284.	4007 REF W/O 13048 Dtd 05/03/09. AD CLOSED.
AD 2008-08-24	NACELLES/PYLONS - STRUT DRAINS AND SEALS - AFT FAIRINGS DRAIN TUBE ASSY REPLACEMENT.	SB 737-54-1043	EO B3-54-1043	4007 REF W/O 13048 Dtd 05/03/09. AD CLOSED.
AD 2008-21-02	NACELLES/PYLONS - HEAT INSULATION BLANKETS - REPLACEMENT.	SB 737-54-1045		SB 737-54-1045 Dtd 07/01/09. REF W/O 13629.
AD 2009-0251E	FIRE PROTECTION - PORTABLE FIRE EXTINGUISHERS IDENTIFICATION/REPLACEMENT.			REF T/LW 2198667/07 Dtd 27 NOV. 09.
AD 2009-0262	FIRE PROTECTION - PORTABLE FIRE EXT. IDENTIFICATION & REPLACEMENT.		SWC926-003	FOUND AFFECTED PIN NOT FITTED.
AD 2009-0278	FIRE PROTECTION - PORTABLE HALON 1211 IDENTIFICATION & REPLACEMENT.		SWC926-004	REF. W/O # 14291. DT. 28/12/09.
AD 2010-01-03	PORTABLE HALON 1211 (BCF) FIRE EXT. MAMTD. BY FFE.			EMB AD 2009-0251E. 2009-0262. FOUND C/W W/ETS AD REGMT. AD CLOSED.

MANDATORY MODIFICATION RECORD

Aircraft Registration A6-DFR
 Owner's Name FOR PRESIDENTIAL FCJ

Mod Ref. No.	Description of Mod	Mod Approval Reference	Reference to other Modifications Affected	Person Certifying Authority, Signature and Date
AD 2009-26-04	MAIN LUG GEAR - FWD TRUNNION PIN INSPECTION AND REPLACEMENT.	SB 737-32-1376		SB FOUND C/W AS PER LHT SB LIST DTD 15/11/07. AD CLOSED.
AD 2009-26-03	ELECTRICAL PANEL - STANDBY STATIC INVERTER MODIFICATION.	SB 737-24-1165		SB FOUND C/W AS PER LHT SB LIST AT TIME OF DEL.
AD 2010-17-05	FUEL PUMP CONTROL GAD FAULT INTERRUPTER (GFI) RELAY INSTALLATION.	B3-281201R1		REF W/O 13629 Dtd 02/09/09.
AD 2010-17-19	ELEVATOR TAB CONTROL MECHANISM DETAILED INSP.	SB 737-27A1297	EO B3-27A1297	SUPERSEDED BY 2013-06-05.
AD 2010-19-03	PREVENT USAGE OF AUXILIARY FUEL TANKS OR MODIFY AUXILIARY FUEL SYS.	SB 5700936NY-D-28-SB-001		SB FOUND UNDER W/O 12640 Dtd 16/08/08.
AD 2011-20-07	FUEL PUMP CONTROL GROUND FAULT INTERRUPTER RELAY INSTALLATION.	SB 737-28A1201R1		REF W/O 13629 Dtd 02/09/2009.
AD 2011-20-10	RUDDER & RUDDER TRIM CONTROL SYS - RUDDER QUADRANT CLEARANCE INSPECTION.	SB 737-27-1282		REF W/O 12252 Dtd 26/11/08.
AD 2011-06-05	MOON OF SLAT TRACK DOWN STOP ASSYS IN ALL L/E SLATS.	SB 737-57A1302		W/O 16115 DTD 16-09-11.
AD 2011-18-10	AFT ENG MOUNT - CENTER LINK ASSY - INSP TO ENSURE CORRECT INSTALLATION.	SB 737-71A1462		W/O 1265007D 14 JAN 08. W/O 12361 DTD 09 MAR 08.
AD 2010-02-04	ENG FUEL FEED - MAIN TANKS ENG FUEL SPAR VLV BODY REPLACEMENT.	SB 737-28-1272		W/O 16115 DTD 16 SEP 11.
AD 2010-27-03	HORIZ STAB TRIM CTRL SYS - STAB TRIM ACT OLN, HOIST BALLSCREW & NUT INSP & LUB.	SB 737-27A1277		
AD 2010-02-04	EXHAUST - THRUST REVERSER INNER WALL MODIFICATION / INSP.	SB 737-79-1082		REF W/O 17078.
AD 2010-24-11	CENTER & OUTER WING - FASTENER SEALING & WIRE BUNDLE SHT - QVI.	SB 737-27A1279		W/O 16115 DTD 16 SEP 11.

MODIFICATION AND REPAIR RECORD

Aircraft Registration A6-DJROwner's Name Presidential Flight

Serial No of Entry	Mod/Repair Ref. No.	Description of Mod/Repair	Mod/Repair Approval Reference	Entry Serial No of other Mods/Repairs Affected	Person Certifying Authority, Signature and Date
193	B3-25-07	EGPT/FURNISHINGS - JT COMPT SEATS - CHANGE TO CAPT/150 SEATS TRACK LOG SPRING	V86		W/O 11673 DTD 16 SEP 11
194	SWC 34-019	EGPWS - TERRAIN DATABASE VER 463 & ENVELOPE MODULATION DB 307.	V53		W/O 17210 DTD 2/1/14
195	B3-Mod-C	ADOPT EXISTING CMSS/IFE TO TW 500 LIVE TV SYS.	Mod "C"	126	W/O 16651 DTD 12/02/12
196	B3-25-1493	INSULATION BLANKET - MOISTURE REDUCTION OF INSULATION BLANKETS AT THE AUTOMATIC OVERWING EXIT DOORS	737-25-493		
197	B3-30-1058	TIE RAIN PROTECTION COIL CORD ASSY. REEL ON THE #2 WINDOW IN THE T/O COMPART	737-30-1058		
198	B3-34-2320	NAV. CPWS - INSTALLATION OF RUNWAY AWARENESS & ADVISORY SYS.	737-34-2320		W/O 17373
199	737-78-1082	INSTN OF A COOLING HOLE & BUSHING, APPLY SEALANT & INSTALL FLANGE INSULATION ASSY ON THE TIREVERSERS.	737-78-1082		DATED 20/02/12
200	B3-2910	POTENTIAL INSUFFICIENT CLEARANCE BETWEEN HYD TUBE & FILTER MODULE	737-SL-29-113		
201	B3-24-200	FIRE PNL WIRE INSTALLATION	737-SL-24-200		
202	B3-32135	SHIMMY DAMPER MOUNTING BOLTS - GRIP LENGTH	737-SL-32-135		W/O 17256 DTD 17-02-12
203	B3-22-1213	YAW DAMPER - DELETION OF YAW DAMPER INDICATOR	737-22-1213		W/O 17508
204	B3-24-1176	AC GENERATION SYS. RE PIN WIRES AT TWO WINGS - TO STRIP ELECTRICAL CONNECTORS AT EACH ENG. AIRCRAFT BRACKET	737-24-1176		DTD
205	B3-29-1111	HYD SYS A/B ENG DRIVEN PUMP - SUPPORT BRKT CHANGE FOR THE HYD PRESS HSG	737-29-1111		10 AUG 2012

MODIFICATION AND REPAIR RECORD

Aircraft Registration A6-DJROwner's Name Presidential Flight

Serial No of Entry	Mod/Repair Ref. No.	Description of Mod/Repair	Mod/Repair Approval Reference	Entry Serial No of other Mods/Repairs Affected	Person Certifying Authority, Signature and Date
206	B3-57-1306 Mod	WINGS - TIE FLAPS - INBD FLAPS - INBD MAIN FLAP TRACKS # 175 EXCH PROGRAM	737-57-1306 Mod		
207	B3-53-098	AIR STAIR DOOR JUMPER POSSIBLY INSTLD INCORRECTLY	737-SL-53-098		W/O 17508
208	B3-57-099	VISUAL AIDS FOR VINYL CRACKS WITHIN NO. 4, 202 - FLT DECK WINDOWS	737-SL		DTD 10 AUG 2012
208	B3-57-099	WING IFE - SLAT DETENT ARM & ROLLER ALIGNMENT.	737-SL-57-099		
209	B3-78-1085	T/R SYS - CHANGE TO THE INSULATION BLANKET ON THE T/R (RH & LH HALF)	737-78-1085		W/O 17218 DTD 10 AUG 12
210	737-78-1088	T/R INNER WALL INST & REPAIR	737-78-1088		W/O 17759 DTD 10 AUG 12
211	SWC 34-019	EGPWS - TERRAIN DATABASE VER 467 & ENVELOPE MODULATION D/B 307	965-1676-34-126		W/O 18508 DTD 18/12/12
212	B3-78-069	T/R LATCH BEAM FAIRING MISSING SEALANT	737-SL-78-069		W/O 18670 DTD 02 FEB 13
213	SWC 34-019	EGPWS - TERRAIN D/BASE VER 468 & ENVELOPE MODULATION D/BASE 307.	965-1676-34-121		W/O 19119 DTD 30-05-12
214	B3-26-1121	FIRE PROTECTION - AIR CARGO - COAST SMOKE DETECTION - INSTALLATION OF	737-26-1121		
215	B3-34-2411	NAV - FLT COMPARTMENT COMPUTER SYS - INSTN OF THE FUTURE AIR	737-34-2411		W/O 18966
216	B3-32188	SHIMMY DAMPER COMPENSATOR MOUNTING BOLTS	737-SL-32-188		DTD 6/6/13
217	737-52-49-092	APU COMBUSTOR DRAIN ADAPTER TORQUE	737-SL-49-092		

MODIFICATION AND REPAIR RECORD

Aircraft Registration A6-DJR

Owner's Name PRESIDENTIAL FLIGHT

Serial No of Entry	Mod/Repair Ref. No.	Description of Mod/Repair	Mod/Repair Approval Reference	Entry Serial No of other Mods/Repairs Affected	Person Certifying Authority, Signature and Date
1	2	3	4	5	6
218	B3-57 ADDN	WINGS - L/E + R/E DEVICES - FUEL DRAIN PATH	737-57-1293		1998 W/O DTD 23-09-13
219	SWC G34-019	EGPWS - TERRAIN D/BASE INSTLN	965-1676-34-126		W/O 19633 DTD 09-10-13
220	B3-34- 2461	NAV-AVC SYS - ROCKWELL COLLUM ATC REPL - ICE + RAIN PROTECTION - COIL CORD ASSY - RALCMT ON #2 WINDOW IN FLT COMPARTMENT	737-34-2461		19805 DTD 14-11-13
221	B3-30 1058	INSPECTION + REPAIR OF THE ENG BUILDUP	737-30-1058		
222	737-71- 1608	BRNTS TO PREVENT DAMAGE TO ENG FAN CASE.	737-71-1608		
223	B3-32- 176	MLG - UPPER TORSION LINK PIN INSPECTION	737-SL-32-176		W/O 19804
224	B3-33- 064	LWR ANTI-COLLISION LIGHT CABLE CHAFING	737-SL-33-064		DTD 4/2/14
225	B3-49 086	APU OIL DRAIN TUBE MISALIGNMENT CAUSING EXTERNAL OIL STREAKING	737-SL-49-086		
226	B3-31- 1471	CD3 - INSTALLATION OF PHASE 3A DISPLAY UNIT + D/BASE SOFTWARE	737-31-1471		W/O 20138 DTD 01-03-14
227	SWCG 34-019	MK V EGPWS; INSTALL A TERRAIN D/BASE + AN ENVELOPE MODULATION D/BASE OF	965-1676-34-126		W/O 20273 DTD 05-03-14
228	B3-34- 2406	REPLACEMENT OF THE TRAFFIC ALERT + COLLISION AVOIDANCE SYS COMPUTER.	737-34-2406		W/O 20359 DTD 26-MAR-14
229	B3-54- 1041	INSTLN OF NEW ENGINE STRUT AFT FAIRING SEALS.	737-54-1041		W/O 16115 DTD 05-09-11
230	B3-21- 1165	AIR COND - CABIN PRESS IND + WARN SYS - REDUNDANT PRESS SWITCH INSTLN	737-21-1165		W/O 20204 08-08-14

MODIFICATION AND REPAIR RECORD

Aircraft Registration A6-DJR

Owner's Name PRESIDENTIAL FLIGHT

Serial No of Entry	Mod/Repair Ref. No.	Description of Mod/Repair	Mod/Repair Approval Reference	Entry Serial No of other Mods/Repairs Affected	Person Certifying Authority, Signature and Date
1	2	3	4	5	6
231	B3-22A 1215	AUTO FLT - AUTO THROTTLE SYS - AUTO-THROTTLE COMPUTER REPLACEMENT	737-22A-1215		
232	B3-25- 1660	EART/FURNISHINGS - ELECTRICAL EART RACK MOISTURE SHROUD - CHANGE	737-25-1660		
232	B3-26- 1131	FIRE PROTECTION - W/WELL, WING + LWR AFT BODY D/INT DETECT SYS - DUCT LEAK D/INT DETECT	737-26-1131		
234	B3-33- 1146	STROBE POSN LIGHTS - LIGHTNING PROTECTION OF THE TAIL STROBE LIGHT SYS WIRING	737-33-1146		
235	B3-34- 2395	LOW RANGE RADIO ALTIMETER - INSTLN OF THE ANTENNA GASKETS	737-34-2395		W/O 20202
236	B3-53- 1307 INSPN	FILLET FAIRINGS - AFT WING TO BODY FAIRING - PNL 194E + AFT CENTER LIAL WLL TAIL 192B - INSPECTION	737-53-1307 INSP		DTD 08-08-14
237	B3-53- 1326	FUSELAGE - CARGO COMPARTMENT SIDEWALL LININGS - INSPECTION + REPAIR	737-53-1326		
238	B3-53- 1341	MISC EXTERIOR SERVICE DOORS - EXTERNAL AIR RECEPTACLE DOOR - BONDING JUMPER	737-53-1341		
239	B3-57- 1316	INSPECTION OF POLYURETHANE PROTECTIVE TAPE ON LWR SKIN SURFACE OF INAD CRND SPANER	737-57-1316		
240	737-78- 1087	THRUST REV SYS - REPLCE OF LOCKOUT HANDLE ASSY ON THE THRUST REVERSER	737-78-1087		
241	737-78- 1090	T/R SYS - INSPECTION FOR + RMVL OF THE T/R INNER WALL COOLING HOLE BLOCKAGE	737-78-1090		
242	737-54- 28-096	ENG FUEL SHUT OFF VALV WIRE CHAFING	737-54-28-096		
243	B3-35- 027	CREW OXY - FLYT NOSE + WIRE BUNDLE INSTLN	737-35-027		

MODIFICATION AND REPAIR RECORD

Aircraft Registration A6-DFR
 Owner's Name PRESIDENTIAL FLIGHT

Serial No of Entry	Mod/Repair Ref. No.	Description of Mod/Repair	Mod/Repair Approval Reference	Entry Serial No of other Mods/Repairs Affected	Person Certifying Authority, Signature and Date
1	2	3	4	5	6
244	83-36025	PRE COOLER CTRL VLV RISS SEAL IMPROVMT	737-SL-36-025		
245	83-53-083	POSSIBLE GAP COMMON TO THE BODY STATION 203 WATER LINE 234 INNER CHORD SPAKE STRUCURE	737-SL-53-083		
246	83-57-106	LH+RH WING NACELLE SUPPORT-OUTRD SHIELD BACKUP FITTING - MISSING FIALET SCW	737-SL-57-106		23/0 20202
247	83-57-109	RESTORATION OF ANA-STATIC COATING COMMON TO THE AILERON FAIRINGS	737-SL-57-109		DTD 08-08-14
248	737-SL-78-076	THRUST REVERSEER BLACKER BOOR SUPPORT LOOSE OR MISSING SCREWS	737-SL-78-076		
249	737-SL-23-048	POSSIBLE INCORRECT ORIENTATION OF CRD CREW HORN.	737-SL-23-048		W/O 21016 DTD 18 OCT 14
250	SWC 34-019	ATERRAIN DATABASE VER 473+ ENVELOPE MODULATION DATABASE 807	985-1476-34-126 737-56		W/O 21182 DTD 30 OCT 14
251	737-24-1205	Electrical Power - Standby Power Sys Replacement of M9 Static Inverter	737-24-1205		W/O 21074 Feb 2015
252	737-26-1131	Fire protection - wheel well etc Refer CRS	737-26-1131		W/O 21074 Feb 2015

ROYAL JET
 PLO4
 09-14-2015

MODIFICATION AND REPAIR RECORD

Aircraft Registration
 Owner's Name

Serial No of Entry	Mod/Repair Ref. No.	Description of Mod/Repair
1	2	3
253		LOG BOOK MAINTENANCE

A/C TYPE	MSN / Prod. No/LINE No	FLIGHT HOURS	F
8737-700	30884	5784:30:00	
ENG TYPE	INSTL PSN	SERIAL NUMBER	TSN
CFM56-7B27/B3	1	876170	1623:55
CFM56-7B27/B3	2	876320	5784.3

APU TYPE	SERIAL NUMBER	TSN
3800702-1	P-5505	11590.7

Performed, A-Check + 2A Check + OOP & Modification as required or requested. All work carried out in accordance with the applicable maintenance program and approved by the competent authority. Royal Jet MP-AMP-737 dated May 2014 and Minor Modification Approval JBSL-M-00/09EN-01.

ITEM	Description
1	Following Directive's
2	737-23-1477 - COMMUNICATIONS - VHF TRANSMITTER AND RADIO TUNING PANELS REPLACEMENT
3	737-23-1479 - COMMUNICATIONS - ACARS - CMU DATA LINK RECORDING INSTALLATION AND C
4	737-23-1482 - COMMUNICATIONS - ACARS - REPLACEMENT OF CMU AIRINC 758 SINGLE ROCKW
5	2006-21-01 LUBE - AILERON BALANCE TAB HINGE BEARINGS AND ROD END BEARINGS LUBRICA
6	737-27-1289 - STABILIZER TAKEOFF WARNING SWITCHES - TEST OF THE TAKEOFF WARNING IND
7	737-27A1277 - HORIZONTAL STABILIZER TRIM CONTROL SYSTEM - BALLSCREW AND NUT INSPEC
8	737-28-1814 - FUEL - ENGINE FUEL SHUTOFF SPAR VALVE ACTUATOR REPLACEMENT
9	737-28A1206 - CWT BOOST PUMP AUTO SHUT OFF AND MASTER CAUTION LOGIC CHANGE
10	737-28A1248 - CWT FUEL PUMP - POWER FAILED ON PROTECTION SYSTEM (UN-COMMANDED F
11	737-30-1070 - ICE AND RAIN PROTECTION - PITOT AND STATIC - POLARITY STANDARDIZATION T
12	737-32-1342 - STEERING - INSP & MODIFICATION TO THE NLD STEERING COLLAR AND STEERING
13	737-32-1448 INSP - MAIN LANDING GEAR - FORWARD AND AFT TRUNNION PIN ASSEMBLIES INC
14	737-34-1043 - NACELLES/PYLONS - STRUT DRAINS AND SEALS - AIT FAIRING DRAIN TUBE ASSEN
15	737-34-1043 - NACELLES/PYLONS - STRUT DRAINS AND SEALS - AIT FAIRING DRAIN TUBE ASSEN
16	737-35-1074 - INSP & REPAIR OF THE INTERFACE BUSHINGS BETWEEN THE HORIZ STAB AND TH
17	JBSL-M-0040SENO - ACARS TO SATCOM INTERFACE MODIFICATION
18	CFM56-7B-72-0909 - FAN AND BOOSTER ASSEMBLY - INTRODUCTION OF A NEW FAN BLADE PLATFORM
19	2015-08-07 - OXYGEN SYSTEM - FLIGHT CREW OXYGEN MASK REGULATOR INFLATABLE

All Work Pack processing has been completed & all Log Books have been updated, signed & stamped.

Name: Muhammad Adeel
 Signature: [Signature]
 Date: 10-Sep-15
 Authority: PLO4
 JSC 1437001

TURKISH AIRLINES TECHNIC Inc.
 Sabiha Gökçen International Airport, Pongik
 34912 Istanbul, TURKEY
 Approval Ref: UAE.145.1081

TURKISH TECHNIC INC.

AIRCRAFT RELEASE TO SERVICE CERTIFICATE

A/C Registration: **A6-DFR** A/C Manufacturer and Type: B737-700
 Date: 30.07.2015 Time: 00:00
 Operator Name: ROYAL JET Start: 22.08.2015 20:20
 Finish: 22.08.2015 20:20

Aircraft	Engine 1	Engine 2	Engine 3	Engine 4	APU
30884	876170	889151			P-5505
Flight Hour	5784:30	1623:55	5784:30		11590.7
Cycle	2070	493	2070		7113

Approved Maintenance Program: HP-AMP-737 Rev. 03 Date: 01.09.2014

Work Order Number: 1380755 Corresponding Maintenance: PERFORM A + OOP CHECK & MODS (705...

Deferred Maintenance Task Cards	Number	Work Order Number
	141-163-164	70533

Deferred Non-Routine Work Items	Number	Work Order Number
	16-41-43-44	70534

Certifies that the work specified except as otherwise indicated was carried out in accordance with CAR 145 and in respect to that work the aircraft/aircraft component is considered fit for release to service.

Certifying Staff: [Signature]
 Authorization Number: 2729 Shop: BASE MAINTENANCE
 Name Surname: IDRIS TUFAN Location: IST
 Issue Date: 28.07.2014
 Form No: MPH L.160/08 R00

