

Sent: Monday, February 22, 2016 10:03:51 AM
From: [REDACTED]
To: jeevacation@gmail.com
Subject: Re: G550

Jeffrey
this G550 has no crew rest,
that is why there are 7 windows that actually are visible in Passenger compartment.
usually if a GV or G550 has a fwd Crew rest area, it takes up passenger compartment space and uses a cabin window inside crew rest area,. or if it has a fwd galley, it blocks cabin window as well. as you know G550 has 7 cabin windows and GV has 6 like our GIV.

example
Lynden Lea's has fwd crew rest and Fwd galley in his GV, he only has 5 windows in his passenger compartment that function to let light in cabin,.

-----Original Message-----
From: jeffrey E. <jeevacation@gmail.com>
To: [REDACTED]
Sent: Mon, Feb 22, 2016 4:27 am

I dont see crew rest?

--

please note

The information contained in this communication is confidential, may be attorney-client privileged, may constitute inside information, and is intended only for the use of the addressee. It is the property of JEE
Unauthorized use, disclosure or copying of this communication or any part thereof is strictly prohibited and may be unlawful. If you have received this communication in error, please notify us immediately by return e-mail or by e-mail to jeevacation@gmail.com, and destroy this communication and all copies thereof, including all attachments. copyright -all rights reserved