
From: ion nicola [REDACTED]
Sent: Thursday, February 17, 2011 3:06 AM
To: Jeffrey Epstein
Subject: RE:

hi jeffrey,

so the doors in the vestibule were supposed to have same design i did on the walls? i didnt know that, garry kerney told me only about the crown molding and the headers on top of the doors..he said not the doors. should i do the doors too?

anyway, now i'm working on the samples for the ceiling in the library..

&n=sp; than=s,

 &n=sp; ion

=3B

Date: Wed, 16 Feb 2011 22:11:09 -0400
From: jeevacation@gmail.com
To: GKerney@landmarklandco.com; ionnicola@hotmail.com; bgordon@nysgmail.com

punch list.. im sure that photos of the vestibule would have saved time and money again, the doors were supposed to receive the same treatment as the walls..i did not receive one photo . the lights in the shower and steam are not working, the switches are not where we agreed. 2. the courtyard lights need to be standardized. the outdoor sconce master bedroom also does not work, the light track light in the office , still needs replacement.

--

The information contained in this communication is confidential, may be attorney-client privileged, may constitute inside information, and is intended only for the use of the addressee. It is the property of Jeffrey Epstein Unauthorized use, disclosure or copying of this communication or any part hereof is strictly prohibited and may be unlawful. If you have received this communication in error, please notify us immediately by return e-mail or by e-mail to jeevacation@gmail.com <mailto:jeevacation@gmail.com> , and destroy this communication and all copies thereof, including all attachments. copyright -all rights reserved

=
=