

To: J Epstein[jeevacation@gmail.com]

Cc: [REDACTED]

From: BMG

Sent: Fri 2/3/2012 2:18:20 AM

Subject: Re:

Power steering fixed

Ran Sunday and had a oil temp alarm on engine 1

Believe it is a faulty sensor

Plan to swap sensor to engine 2 to confirm

FYI outside of this , this hull rode 6ft seas with no problem Will bring to LSJ for weekend

Brice

Sent from my iPhone

On Feb 2, 2012, at 8:34 PM, [REDACTED] > wrote:

> JE is asking when midnight express is going to be ready.