

**To:** jeffrey E.[jeevacation@gmail.com]  
**From:** Larry  
**Sent:** Sun 7/27/2014 9:09:45 PM  
**Subject:** Re: Bedford crash update

Jeffrey,

I haven't heard any real updates other than, gust lock position appeared to be if OFF position, which explains why throttles we're able to reach takeoff power, if gust lock was actually engaged, throttles would only accelerate to 6%.. I still believe pilots didn't not accomplish a freedom of movement prior to departure, coupled with a failed Gust lock Elevator control link,

June 16 post:

National Transportation Safety Board (NTSB) investigators are closely analyzing the contents of cockpit voice and flight data recorders recovered intact from the wreckage of the Gulfstream IV that crashed May 31 on takeoff from Bedford-Hanscom Field (BED) in Massachusetts. The accident killed all four passengers and three crew on board.

In a televised briefing last week, NTSB investigator-in-charge Luke Schiada said the recorders provide solid information until the moment of the crash off the end of BED's 7,011-foot-long Runway 11. The aircraft takeoff roll lasted 49 seconds before the recordings were terminated, with normal V-speed callouts occurring during takeoff until the moment of rotation when pilot conversation about aircraft controllability could be heard. The GIV reached 165 knots but never left the ground and the crew attempted to abort the takeoff, deploying maximum reverse thrust in the process.

The airplane was unable to stop on the remaining runway and crashed into a gully about 2,000 feet beyond the departure end of the pavement and was subsequently destroyed by fire. Schiada said the aircraft's takeoff weight and flap settings are still being determined, and that airport surveillance camera footage has yet to be analyzed.

Sent from my iPad

On Jul 27, 2014, at 10:47 AM, "jeffrey E." <jeevacation@gmail.com> wrote:

any more on the plane crash in bedford?

--

please note

The information contained in this communication is confidential, may be attorney-client privileged, may constitute inside information, and is intended only for the use of the addressee. It is the property of JEE

Unauthorized use, disclosure or copying of this communication or any part thereof is strictly prohibited and may be unlawful. If you have received this communication in error, please notify us immediately by return e-mail or by e-mail to [jeevacation@gmail.com](mailto:jeevacation@gmail.com), and destroy this communication and all copies thereof, including all attachments. copyright -all rights reserved