

To: jeevacation@gmail.com[jeevacation@gmail.com]
From: [REDACTED]
Sent: Tue 3/19/2013 4:19:59 AM
Subject: GIV interior

Jeffrey,
Gulfstream Avionics will have answer tomorrow regarding what interior components are required to be removed for Cockpit DU885 upgrade,. Avionic Sales person Tom Balia indicated headliner removal for XM Weather antenna, and side panels in cockpit for installation of mouse control of LED screens, he didn't think it was full interior removal, depends on location of antennas,.
more information Tuesday afternoon.

thx,
Larry