

To: Larry Visoski [REDACTED]
From: Jeffrey Epstein
Sent: Wed 1/23/2013 2:45:20 AM
Subject: Re: GII update

ok

On Tue, Jan 22, 2013 at 9:37 PM, Larry Visoski <[REDACTED]> wrote:

Jeffrey,
Gulfstream has determined pitch computer is faulty, we will warranty exchange the pitch computer. The only available pitch computer is located in Ohio and is currently being rush shipped to Honeywell in California for re-certification, we put a rush order to get part completed asap with arrival Thursday or Friday the latest.
During our trouble shooting today, the Avionic tech noticed erratic movement in control yoke while commanding pitch inputs thru autopilot pitch control knob, it was intermittent but enough to show some type of malfunction in pitch control.
My plan is to take Gulfstream Technicians for a test flight once part is installed to verify its operation. Since Gulfstream Savannah Tech support is spearheading this trouble shooting, I have to follow their recommended trouble shooting techniques. Since we have replaced this pitch computer recently , Gulfstream indicates its not uncommon to get a bad part, my altitude hold issues points toward this pitch computer again.

i'd like to airline home tonight and return when I have firm arrival date of Pitch computer?

is this approved?

thank you,
Larry

Sent from my iPad

--

The information contained in this communication is confidential, may be attorney-client privileged, may constitute inside information, and is intended only for the use of the addressee. It is the property of Jeffrey Epstein

Unauthorized use, disclosure or copying of this communication or any part thereof is strictly prohibited and may be unlawful. If you have received this communication in error, please notify us immediately by return e-mail or by e-mail to jeevacation@gmail.com, and

destroy this communication and all copies thereof,
including all attachments. copyright -all rights reserved