

To: Jeffrey Epstein[jeevacation@gmail.com]
From: Ann Rodriquez
Sent: Wed 4/2/2014 7:34:01 PM
Subject: Fwd: Sportis shipment

Ann R.

Begin forwarded message:

From: Ann Rodriquez [REDACTED]
Date: April 2, 2014 at 3:29:13 PM AST
To: Adam Zygowski [REDACTED]
Cc: Richard Kahn [REDACTED], Daphne Wallace
[REDACTED], Carlos Rodriguez [REDACTED]
Subject: Re: Sportis shipment

Hi Adam,

As stated earlier in my email the issue is not the Engines it is the Noise coming from the hull.

Once the Sportis is in the Water you will be able to hear the ear soar of water splashing against the hull. I do apologize for any inconvenience this may have caused but the Sportis is just a very noisy boat Sitting at the dock or out on the Ocean.

Ann R.

On Apr 2, 2014, at 3:09 PM, "Adam Zygowski "
[REDACTED] wrote:

Hi Ann,

As mentioned earlier to Carlos, obviously we cannot test the boat without engines.

We do not have test 300 hp engines - and cannot use new engines, otherwise they are not new anymore when we use them for 5-10 hours.

I recommended to change the position of the engines by regulating them up/down on the regulation screws - not to change them completely to other ones.

Best regards

Adam Zygowski

Dnia 02-04-2014 o 18:37:02 ann rodriguez

[REDACTED]napsal(a):

Hi Adam,

We have removed our engines to ship the Sportis back to Poland this week.

Our problem with the Sportis is a noise and hull issue not an engine issue, I was informed by 2 Boat captains that changing the engines will not make a difference because it will still sound the same. Please use what ever engines you may have in stock or on hand to test the Sportis to determine the noise and hull issue.

Thank You,

Ann R.

[REDACTED]

DISCLAIMER: The information contained in this e-mail may be privileged, confidential, and protected from disclosure. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or duplication of this communication is strictly prohibited. If you have received this communication in error, please notify the sender immediately and delete all copies.

On Wednesday, April 2, 2014 9:28 AM, Carlos Rodriguez [REDACTED] wrote:

On Tuesday, April 1, 2014 3:49 PM, Adam Zygowski
[REDACTED] wrote:

Carlos,

If you remove the engines we will not have the possibility
to test theboat...

And will not know if our works bring the expected result.

We do not have two 300 hp test engines.

Please leave

them mounted.


Dnia 01-04-2014 o 21:11:24 Carlos rodriguez
[REDACTED] napisal(a):

This is the trailer the install for lights is 12
volt


--

SPORTIS S.A.

[REDACTED]
ul. Na Dambnik 22, Bojano Poland



www.sportis.com.pl



Rejestracja: Sąd Rejonowy Gdańsk Północ Oddział w Gdańsku,
VIII Wydział Gospodarczy KRS nr 0000067475,
kapitał zakładowy: 2.058.170 PLN w całości opłacony.
Regon 191726929, NIP 588-18-40-279

Registered with no: 0000067475 in Regional Court Gdańsk-Północ in
Gdańsk.

Share capital: 2.058.170 PLN Paid. VAT UE: PL 5881840279
