

**To:** Jeffrey Epstein[jeevacation@gmail.com]  
**From:** Larry  
**Sent:** Thur 1/30/2014 1:36:48 AM  
**Subject:** Re: GV

We are looking at serial #506 with HUD, which means it's the 6th GV to be manufacture. There were 191 GV's manufactured.

I'll check with Pruitt, he has a close serial number GV serial #519 with 4537 total time on Controller, No HUD. This would be a good comparison,


Serial number #526 has asking price of \$14.5M higher total time 8460 No HUD.

Wednesday, January 29th, 2014

## 1997 GULFSTREAM V

[Financial](#)

[Add To V](#)



### Equipment Specifications

<b>Year</b>	1997
<b>Manufacturer</b>	GULFSTREAM
<b>Model</b>	V
<b>Price</b>	\$14,500,000
	AED
	ARS
	AUD
	BGN
	BOB
	BRL
	BZD
	CAD
	CHF
	CLP
	CNY
	COP
	CRC
	CZK
	DKK
	EEK
	EGP
	EUR
	GBP

GTQ  
HKD  
HNL  
HRK  
HUF  
IDR  
ILS  
INR  
JOD  
JPY  
KRW  
LBP  
LKR  
LTL  
MAD  
MXN  
MYR  
NIO  
NOK  
NZD  
PAB  
PEN  
PKR  
PLN  
PYG  
QAR  
RON  
RSD  
RUB  
SAR  
SEK  
SGD  
THB  
TND  
TRY  
TWD  
UAH  
USD  
UYU  
VEB  
VEF  
ZAR

**Location** Houston, Texas  
**Condition** Used  
**Serial** 526

<b>Number</b>	
<b>Registration Number</b>	N125GH
<b>Total Time</b>	8460 Hours

### General Information

WiFi Internet Connection, 14 Passenger Seating, Engine Overhaul Completed October 2012.

### Detailed Description

#### Airframe:

Aircraft Total Time: 8460.4

Aircraft Landings: 3042

Aircraft Basic Operating Weight 48,401.6

#### Engine Specs:

Engines BR710-A1-10 TSN: 7912.6

Engines enrolled in Rolls Royce Corporate Care Program

Auxiliary Power Unit (APU) S/N P-127: 5543 TT

(Not enrolled in MSP)

#### Avionics/Radios:

Honeywell SPvZ-8500 Cockpit Suite integrated

Three Honeywell Flight Management Systems at Software Level 6.0

Third IAC-800 installed for NZ-2000 function

FMS CDUs upgraded to CD-820

Dual 12 Channel Global Positioning Satellite Systems

TCAS Traffic Collision Avoidance System? ACASII Change 7

AFIS (ARINC Direct) VHF and Satellite Communication System

Honeywell Primus 880 Weather Radar System

Triple Rockwell Collins VHF Communication Systems with 8.33 kHz spacing

Dual Honeywell Mode S Transponders with Flight ID, Enhanced Surveillance exemption

Honeywell Mark V Enhanced Ground Proximity Warning System

Dual Rockwell Collins HF-9000

Selcal

GH-3000 Secondary Flight Display w/Magnetometer input

Magnastar C-2000 Radio-Telephone with five handsets, (One Cockpit, three Cabin, one galley) with visible cockpit call alert.

Honeywell MCS-6000 Inmarsat Satellite Telephone System interfaced to the Magnastar Handsets, AFIS and

Airshow Display

XM Weather Satellite feed installed for use with portable EFBs

Artex 406 Emergency Locator System  
Pulselight Visual System

**Additional Equipment:**

Crew Jumpseat with audio control panel  
Airshow 4000 Cabin Information System  
Audio International/Pacific Systems Cabin  
Entertainment System:  
Airshow, DVD, VCP & CD Players  
Three Rosen 15" LCD Monitors in the cabin  
Rosen 5.6" Monitor in Crew Rest Area  
3.5 KVA 60Hz Converter  
Three Observation Cameras

**Exterior:**

White with Red, Black and Titanium Stripes

**Interior:**

Passenger Seating 14, 6 Individual Chairs, 4-place Conference Group w/table, one 4-place Divan, 2  
Kibitzer opposite  
conference table (Not certified for T/O & Landing)  
Fwd 3rd Crewmember Jump Seat.  
Fwd Crewmember Rest Area w/Lav  
Aft Galley  
Aft Lav

**Inspection Status:**

Maintenance:  
Engines:  
Overhaul Completed October 2012  
Airframe  
96 Month Scheduled Maintenance  
Completed August 2006

**Say you saw this 1997 GULFSTREAM V On [Controller.com](http://Controller.com)!**

**[Send Wing Aviation A Message](#)**

Contact:  
Wing Aviation  
Aircraft Located in:  
Houston, Texas

Phone: [\(866\)944-9464](tel:(866)944-9464)


[Return To Previous Page](#)

[Home](#) [Copyright & Legal Notice](#) [Privacy Policy](#) [Site Map](#) [Contact Us](#)  
Copyright © by Sandhills Publishing Company 2014. All rights reserved.

# 1997 GULFSTREAM V

[Financial](#)

[Add To V](#)



Equipment Specifications	
Year	1997
Manufacturer	GULFSTREAM
Model	V
Price	Call
Location	Colleyville, Tex
Condition	Used
Serial Number	519
Registration Number	N526EE
Total Time	4538 Hours

## General Information

Interior updated in '07. 14 Passenger layout. Forward Cabin 4 single club seating. Mid Cabin 1 4-pl

berthable divan with opposite 2 seats.

### Detailed Description

#### Airframe:

Aircraft Total Time: 4537.5

Aircraft Landings: 1284

#### Engine Specs:

Engines: BMW Rolls-Royce Engines BR710A1-10- Enrolled on Rolls-Royce Corporate Care

#1 Engine Serial Number: 11143 #2 Engine Serial Number: 11142

Total Time: 4466.0 Total Time: 4537.5

Total Cycles: 1267 Total Cycles: 1284

Time to Overhaul: 3534 Time to Overhaul: 3462.5

APU Serial Number: P-117

Total Time: 3710

AlliedSignal RE220 Enrolled on MSP

#### Avionics/Radios:

Honeywell SPZ-8500 Flight Director

Dual Collins VIR-432 VHF NAV

Dual Collins DME-442 DME

Dual Collins HF-9000 HF COMM

Dual Honeywell RT-300 Radio Altimeter

Triple Honeywell Laseref III IRS

Honeywell Primus 880 Color Radar

B&D Instruments 89098-0031 CVR

Honeywell LSZ-850 Lightning Detection

Honeywell Primus 880 Stormscope

Dual Collins VHF-422C VHF COMM

Dual Collins ADF-462 ADF

Dual Collins TDR-94D Mode S Transponder Mode

Dual Collins RTU-4280 Radio Freq Mgt

Dual Honeywell IC-800E Integrated Avionics

Dual Honeywell HG-2021 12 Channel GPS

Dual Honeywell NZ-2000 FMS

B&D Instruments 91005-0031112 FDR

Honeywell DL-950 Data Loader

#### Additional Equipment:

Allied Signal Mark V EGPWS with RAAS / TCAS II with Change 7 / Pacific Systems Membrane Swit

Magnastar C-2000 Radio Telephone / Allied Signal AFIS w/SATCOM Link and Cockpit Printer / Hor

MCS-6000 SATCOM (\*inactive) / ICS-120 Iridium phone with AFIS link / Artex 406 Emergency Loca

System / Airshow Genesys / FMS 6.0 / 8.33 kHz / 60 Hz outlets in cockpit

#### Exterior:

New paint in '09. Painted overall Matterhorn White w/ Midnight Blue bottom and Coronet Gold stripe

**Interior:**

Interior updated in '07. 14 Passenger layout. Forward Cabin 4 single club seating. Mid Cabin 1 4-plate berthable divan with opposite 2 seats. Aft Cabin 4 single club seating. Aft Galley, Aft and Forward V Lavatories. Aft Galley includes: convection microwave, coffee maker, hot cup, regular ice drawers and large ice drawer. Extra large coat closet in vestibule and Aft Lavatory. Colors: Seats: Ivory leather, D Light Beige Fabric, Wood: European Beach, Headliners: Off white ultra suede, Metal: Golf Finish and Beige Entertainment: DVD/CD Player, 10 CD Changer, 20" LCD monitor on Forward bulkhead, 17" LCD monitor on Aft bulkhead, 15" LCD monitor on right hand Forward Cabin panel.

**Inspection Status:**

Specifications are Subject to Verification by Purchaser. Aircraft is Subject to Prior Sale, Lease, and/ Removal from the Market without Prior Notice.

**Say you saw this 1997 GULFSTREAM V On [Controller.com](http://Controller.com)!**

**[Send Jack Prewitt & Associates A Message](#)**

Contact:

[Jack Prewitt & Associates](#)

Aircraft Located in:

Colleyville, Texas

Phone: [\(817\)283-2826](tel:(817)283-2826)

Fax: [\(817\)267-4805](tel:(817)267-4805)

[Return To Previous Page](#)

Sent from my iPad

On Jan 29, 2014, at 7:25 PM, Jeffrey Epstein <[jeevacation@gmail.com](mailto:jeevacation@gmail.com)> wrote:

call some of the other g 5 s on controller and get comparison, . jack pruit etc.

--

\*\*\*\*\*

The information contained in this communication is confidential, may be attorney-client privileged, may constitute inside information, and is intended only for the use of the addressee. It is the property of Jeffrey Epstein

Unauthorized use, disclosure or copying of this communication or any part thereof is strictly prohibited and may be unlawful. If you have received this communication in error, please notify us immediately by return e-mail or by e-mail to [jeevacation@gmail.com](mailto:jeevacation@gmail.com), and destroy this communication and all copies thereof, including all attachments. copyright -all rights reserved