

To: Jeffrey Epstein[jeevacation@gmail.com]
From: Eric Roth
Sent: Tue 12/10/2013 8:35:30 PM
Subject: RE:
[image001.jpg](#)
[image002.jpg](#)
[image003.jpg](#)

December 9, 2013

Gulfstream IV, Serial No. 1085, Registration No. N212JE

Air Gaspers -

Squawk: Cabin area air gaspers do not seat 100% and the pressure causes a “hissing sound”.

Status: Larry has procured gaspers and plenums. We noticed that they did not come with the wire clamps, so we will have to order them for you. We shipped one gasper overnight to Larry for delivery on 12/10 so that he may show it to you to identify if you want them plated or not.

Est. Time Required: Metal plating will take approximately 10 – 12 days. Once gaspers are ready for installation, IJI will require 3 -4 days to trim escutcheons and install the gaspers.

Upwash Lighting-

Squawk: Various light fixtures are intermittent.

Status: Each light bulb and associated power supply ballast will need to be tested. IJI recommends replacing the light bulbs as a means of testing and perhaps more importantly to have even coloration throughout the cabin.

Est. Time Required: IJI will require 1 – 2 days to troubleshoot. Dependent upon finding, it may take 1 – 3 days to correct.

R/H #2 VIP Master Switch Panel-

Squawk: Client would like to have the R/H #2 master switch panel reworked by manufacturer to have it reprogrammed to control the shades “ALL UP” and “ALL DOWN”.

Status: The switch panel was going to be removed at Gulfstream and sent to the manufacturer for a return on the 20th and I found out today that this is not going to happen.

Est. Time Required: Manufacturer has stated they will “commit” to a two (2) week turn around to reprogram the panel and replace a few internal parts.

Window Shades-

Squawk: Pleated window shade material within the window panel assemblies in the main cabin are “wrinkled” at the pleats.

Status: We sent an e-mail with photo’s and waiting for vendors response including downtime required.

Est. Time Required: Waiting on vendor.

Table Lid-

Squawk: Client would like to route the inboard vertical surface to provide an easier opening of lid.

Status: IJI has identified ½ moon shape and rectangular shape. Need JE decision..

Est. Time Required: Route and paint to coordinate – 2 days.

Maintenance Runner-

Squawk: Need to fabricate vinyl maintenance runner.

Status: Waiting on color choice by JE.

Est. Time Required: 2 days after receipt of material (material should be in stock).

Fwd Cabin Monitor-

Squawk: Fwd cabin monitor is faulty.

Status: Sent monitor to manufacturer for warranty. Replaced with temporary monitor which has been determined by Gulfstream Savannah to also be faulty. Informed manufacturer that client is very unhappy with this model and that he would like to move away from this model and replace it with a HD monitor.

Est. Time Required: Waiting on reply from manufacturer to see if they will accept the return and provide a credit towards a new HD monitor.

Entertainment System -

Squawk: JE wants to upgrade system.

Status: Larry is testing the Bose system to see if JE likes it.

Est. Time Required: Once JE has identified that he would like to move in this direction, we will prepare a quote including cost and time required.

ERIC H. ROTH | PRESIDENT



P [REDACTED] 3 | [REDACTED] www.intljet.com  

2221 Smithtown Avenue, Long Island MacArthur Airport, Ronkonkoma, New York 11779

From: Jeffrey Epstein [mailto:jeevacation@gmail.com]
Sent: Tuesday, December 10, 2013 3:37 PM
To: Eric Roth; Ivjet; Richard Kahn
Subject:

you told me i would receive a detailed scedule either late yesterday or this morning, both have past

--

The information contained in this communication is confidential, may be attorney-client privileged, may constitute inside information, and is intended only for the use of the addressee. It is the property of Jeffrey Epstein

Unauthorized use, disclosure or copying of this communication or any part thereof is strictly prohibited and may be unlawful. If you have received this communication in error, please notify us immediately by return e-mail or by e-mail to jeevacation@gmail.com, and destroy this communication and all copies thereof, including all attachments. copyright -all rights reserved