

To: Jeffrey_Einstein[eevacation@gmail.com]
Cc: [REDACTED]
From: Eric Roth
Sent: Fri 6/7/2013 6:27:55 PM
Subject: Metal Plating
[image007.jpg](#)
[image008.jpg](#)
[image009.jpg](#)

Jeffrey-

All of the metal plating has been plated and has been shipped back to us.

The items that have not been plated are the switch panels, the air gaspers and the reading / table lights and the UBS charging ports.

With regard to you recent request to have certain items plated, we need to know "which items specifically" were you thinking of. Obviously there will be an additional cost if newly plated items need to be stripped and replated in chrome.

ERIC H. ROTH | PRESIDENT



2221 Smithtown Avenue, Long Island MacArthur Airport, Ronkonkoma, New York 11779