

Jeffrey,  
after reviewing my notes on the budget to repair the Bell 430, you mentioned a cost of \$350k for repair work, actually the known items needing to be completed to make airworthy are: \$293,393.14 the additional \$59,819.34 was interior work, which in my opinion is high, we should be able to get better pricing in USA, if you would prefer to accomplish interior once helicopter arrives in USA.  
Estimated Labor charge for maintenance requested:

Labor f24,275.00 pounds sterling = USA \$37,805.64	
Parts estimated: =	\$255,587.50
<hr/>	
total for Maintenance	\$293,393.14

Interior quote in Pounds f38,410.00= 59,819.34  
USD: Total \$353,212.48 maintenance and interior from PremiAir in UK,.

Jeffrey, this is my rough draft for your approval, if you could critique ?

Mr. Craig Lamminman,

We would like to offer the following conditions in the purchase of N901RL a Bell 430 helicopter.

- Purchase price to be \$1,600,000.00 USD "As is, Where is"
- A refundable \$100,000.00 would be paid to escrow, Buyer has right to complete oil analysis of engines, tail rotor gear box and main rotor gear box at buyers expense.
- PremiAir will be contracted to completed the quoted work scope estimate below, at requested reduced price of \$250,000.00 USD.
- it is understood there will be discrepancies found and will be subject to buyers approval, repaired at current shop hourly rate, and will be considered over and above the fix quote provided by PremiAir.

-I am5448

Delivered-To: jeevacation@gmail.com

Received: by 10.68.212.73 with SMTP id ni9cs16463pbc;  
Thu, 26 Jan 2012 10:25:01 -0800 (PST)

Received: by 10.52.68.132 with SMTP id w4mrl634517vdt.124.1327602300875;  
Thu, 26 Jan 2012 10:25:00 -0800 (PST)

Return-Path: <[REDACTED]>

Received: from mail-vw0-f45.google.com (mail-vw0-f45.google.com [209.85.212.45])  
by mx.google.com with ESMTPS id jb4si2615804vdb.29.2012.01.26.10.25.00  
(version=TLSv1/SSLv3 cipher=OTHER);  
Thu, 26 Jan 2012 10:25:00 -0800 (PST)

Received-SPF: pass (google.com: domain of [REDACTED] designates  
209.85.212.45 as permitted sender) client-ip=209.85.212.45;

Authentication-Results: mx.google.com; spf=pass (google.com: domain of  
[REDACTED] designates 209.85.212.45 as permitted sender)

smtp.mail.[REDACTED]; dkim=pass header.i=@gmail.com

Received: by vbbey12 with SMTP id ey12so644932vbb.4  
for <jeevacation@gmail.com>; Thu, 26 Jan 2012 10:25:00 -0800 (PST)

DKIM-Signature: v=1; a=rsa-sha256; c=relaxed/relaxed;  
d=gmail.com; s=gamma;

h=subject:references:from:content-type:x-mailer:in-reply-to  
:message-id:date:to:content-transfer-encoding:mime-version;

bh=+0ouSte95n5DlBug+a/2aTmFKe8zJnVrNX1PnkpzETo=;

b=JtOKppDvqYK57VAsVMtyQz6qfPHWwo7UGHF/4ubRrRMYvM3VMKXKU0ujODkBcn2O60  
wOPKBSNqczZSyIBip5GIiqDdmjvPz8CrP15+TCKtPBKFi4myhm7hknJMN/FEL+r+X3QO  
y5da6DEg4ERVfV2PcRKcoZynGlm9WS4wL7wq8=

Received: by 10.52.34.167 with SMTP id a7mrl1507066vdj.123.1327602300448;

Thu, 26 Jan 2012 10:25:00 -0800 (PST)  
Return-Path: <[REDACTED]>  
Received: from [10.112.252.159] (mobile-166-137-137-246.mycingular.net.  
[166.137.137.246])  
by mx.google.com with ESMTPS id ei6sm4603557vdc.6.2012.01.26.10.24.57  
(version=TLSv1/SSLv3 cipher=OTHER);  
Thu, 26 Jan 2012 10:24:58 -0800 (PST)  
Subject: Re: Ren  
References: <62DB29E6-1334-4841-9FC0-476D7B28CC48@gmail.com> <CA+t=u-  
ZviuKFK8Tkm5cX2so7pt5cFQq03o+qa\_AjEVar+pwaEg@mail.gmail.com>  
From: [REDACTED] <[REDACTED]>  
Content-Type: multipart/alternative;  
boundary=Apple-Mail-E89B00B1-D037-4BB0-A4EA-9111A4906B64  
X-Mailer: iPhone Mail (9A405)  
In-Reply-To: <CA+t=u-ZviuKFK8Tkm5cX2so7pt5cFQq03o+qa\_AjEVar+pwaEg@mail.gmail.com>  
Message-Id: <01A0C99A-9BFC-477C-A8DB-BEF622B6F798@gmail.com>  
Date: Thu, 26 Jan 2012 13:24:58 -0500  
To: Jeffrey Epstein <jeevacation@gmail.com>  
Content-Transfer-Encoding: 7bit  
Mime-Version: 1.0 (1.0)