
From: Brice Gordon [REDACTED]
Sent: Tuesday, February 6, 2018 8:24 PM
To: Russell Hernandez; jeffrey E.; Rich Kahn
Subject: Re: Man Hole

Hi =ussell
confirm=ng from Danny, yes, rebar was drilled to existing concrete manhole.
<=div>

On Mon, Feb =, 2018 at 3:31 PM, Russell Hernandez [REDACTED] wrote:

great thank you could you please confirm that the rebar was drilled into=the existing concrete i have added
mark (shark) from ASC as well

<=div>
we can see the rebar in the photo but can't see the connectio=

also every block should have rebar

thank you

IMG_3618.JPG

IMG_3=19.JPG <https://drive.google.com/file/d/1yv=eoUFlzwZE3x6w-bPJwmWSxsbk9eGy/view?usp=drive_web>
<https://ssl.gstatic.com/docs/doclist/images/icon_10_gen=ric_list.png> IMG_3620.JPG

<https://drive.google.c=m/file/d/1RGL1jaoQP8q4hkxCHsC0mC-lcB0kEDWQ/view?usp=drive_web>
IMG_3622.JPG <https://drive.google.com/file/d/1YjX7VG6RihYbNxdbgay3=wakq4cg3g9A/view?usp=drive_web> =img
style="display:none;opacity:0.55;float:right">
=8B
=C2 IMG_3624.JPG <https://d=ive.google.com/file/d/1P-E-q-NKrM7OBjsxdl5uTg7ofxzceM34/view?usp=drive_w=b>

IMG_3625.=PG
<https://drive.google.com/file/d/1V7ew0o=DRmtwaBLmutglgKp8tRWFeWoC/view?usp=drive_web>
=E2
<https://ssl.gstatic.com/docs/doclist/images/icon_10_gener=c_list.png> IMG_3626.JPG

--
=div class="gmail_signature" data-smartmail="gmail_signature"> Brice Gordon<=iv>

Stanley, NM

LSJ-GSJ, =SVI

Ph: ([REDACTED]
=/div>