

From: [REDACTED] <[REDACTED]>
To: "Robert" <[REDACTED]>
Subject: Re: Add to PUNCH LIST
Date: Mon, 12 May 2014 20:18:04 +0000

thanks

On May 12, 2014, at 4:14 PM, "Robert" <[REDACTED]> wrote:

> ok

>

> -----Original Message-----

> From: [REDACTED] [mailto:[REDACTED]]

> Sent: Monday, May 12, 2014 1:02 PM

> To: Bob Caffrey

> Cc: [REDACTED]

> Subject: Add to PUNCH LIST

>

> Hello Bob...we were at house yesterday and noticed the below..you may have
> on your punch list already, but if not...here you go!

>

> -Front Door has a gap at the bottom where the 2 doors come together...you
> can see daylight shining through! Gap should be sealed.

>

> -Foyer Chandelier not wired properly...if you turn on at bottom of
> staircase, you can't turn off at top of stair case and vice versa...you
> should be able to turn off or on no matter where you have last turned
> off/on...right?

>

> -Master Bath shower head is loose...the whole thing rotates...needs to be
> screwed in tighter?

>

> -Sliding door in Master Bedroom, right hand side-when entering from the
> vestibule-the hardware hits the trim and it doesn't slide properly because
> of this...

>

> -Sink in the mud room is still not sitting properly...caulk is pulling up
> already...maybe sink needs to come out and pushed back in?

>

> -The door in mud room leading to side of house: look at the trim on the
> door...there are large holes for every screw/nail(?) that was used to attach
> the trim...shouldn't that be filled in?

>