

From: Marie-Joseph Experton <[REDACTED]>

To: 'bellaklein' <[REDACTED]>, [REDACTED]

Cc: 'Darren Indyke' <[REDACTED]>

Subject: EPSTEIN / steam and water pressure

Date: Fri, 21 Dec 2012 19:51:11 +0000

Importance: High

Attachments: DevisPompeJacuzzi21dec12.pdf

See attachment: quote for the water pump.

Best regards.

Marie-Joseph Experton

Avocat au Barreau de Paris établi à Bruxelles

From: Marie-Joseph Experton [mailto:[REDACTED]]

Sent: vendredi 21 décembre 2012 18:53

To: 'bellaklein'; [REDACTED]

Cc: 'Darren Indyke'

Subject: EPSTEIN / steam and water pressure

FYI:

1.

When Mr. Epstein was in Paris last, he asked Valdson to have a technician looking at the fact that the **steam pressure** in the « *hammam* » (turkish baths) next to the massage room is not sufficient. The technician verified the system and says that with the existing installation, the pressure cannot be increased. The only possibility according to him, could be (but he was not sure) to replace the system by new machinery. I understand that Valdson informed [REDACTED] about this.

2.

In the same bathroom, Valdson found that the **water pressure** in the shower is not sufficient either. He asked the technician to have a look at it. The technician explained that the water pump needs to be replaced. Valdson is expecting a quote for that, but he has not yet received it.

Best regards.

Marie-Joseph Experton

Avocat au Barreau de Paris établi à Bruxelles