

Emad Hanna

From: Jeffrey Epstein [REDACTED]
Sent: Wednesday, October 06, 2010 6:15 PM
To: bgordon.lsj contact
Cc: Emad Hanna
Subject: Re: Zorro: Fountain and terrace invoices

pay , except for extra , pay 1140 terrace , and the original estimate of 26

On Wed, Oct 6, 2010 at 10:15 PM, brice gordon <[REDACTED]> wrote:
Jeffrey

For your approval

attached are the corrected invoices from JJ for the installation of the water proof membrane on the Master bedroom terrace and the lowering of the fountain at Zorro.

Terrace Work dated 8/19/10
Cost: \$1140.00

Fountain bowl lowering , dated 8/18/10 and 9/8/10
Cost: \$3883.50

Brice

--

The information contained in this communication is confidential, may be attorney-client privileged, may constitute inside information, and is intended only for the use of the addressee. It is the property of Jeffrey Epstein
Unauthorized use, disclosure or copying of this communication or any part thereof is strictly prohibited and may be unlawful. If you have received this communication in error, please notify us immediately by return e-mail or by e-mail to [REDACTED], and destroy this communication and all copies thereof, including all attachments.

Three B's LLC
6023 Osuna NE
Albuquerque, NM 87109
Lic.# 83498
Invoice

Zorro Ranch
Stanley, NM

10/6/10

Install self adhesive water proofing material on deck outside mater bedroom to protect lower terrace ceiling from water damage. This material is only a temporary fix and will not withstand the elements for longer than 6 months.
Wok was completed on 8-19-2010

Material 750.00
Labor 390.00
Tax 77.00
Price 1,140.00 plus tax

Total due \$1,217.00

✓ OK per JE

Please call me if you have any questions at 450-3654.

Thank you,

JJ Blea

Three B's LLC

4600 Lincoln rd. NE
Albuquerque, NM 87109
Lic.# 83498
505-450-3654
Invoice

Zorro Ranch
Stanley, New Mexico

06 October, 2010

Phase 1 8/18/2010

Support fountain bowl with I-beams and heavy duty material lifts (4)

Saw cut grout joint

Raise bowl and remove middle piece of fountain.

Lower bowl and set into place for owner to approve

Cost: \$2450.00

Tax: 171.00

Total: \$2621.50

Phase 2 9/8/2010

Support fountain bowl with I-beams and heavy duty material lifts (4)

Raise fountain and apply grout

Lower fountain to height indicated by owner and level

Fill bowl to check for uniformity of water flow around the perimeter of bowl. Some grinding may need to be done to achieve water flow.

Cost: \$1,180.00

Tax: \$ 82.00

Total: \$1262.00

Includes; material, labor, equipment to complete project

Excludes; electrical and plumbing

* Fountain to be lowered after the 17th of August and to be completed before owner returns on the 21st of August so that owner can confirm height.

Material 400.00

Equipment rental 1200.00

Labor 2030.00

Tax 253.00

Final total \$ 3,883.50

Call me if you have any questions at 450-3654

Thank you,

JJ Blea

ZORRO # 55
only amounts JE approved add to stonework change order