

November 19, 2013
 North Solar Screen
 9 Bartlet Street
 Suite 231
 Andover, MA 01810
 Phone: [REDACTED]
 Fax: [REDACTED]

I, _____, authorize North Solar Screen to charge the credit card # given over the telephone. Here are the LAST FOUR DIGITS ONLY: _____, expiration date _____, to pay for this order. My signature above confirms that the materials and dimensions are correct. I understand that this custom order can't be returned, or refunded unless it is not manufactured to the specifications herein described, or the fabric or components are defective.

North Solar Screen - Order Confirmation #14308D

Billing Address

Mark Tollison
 [REDACTED]

Shipping Address

Mark Tollison
 [REDACTED]

Number	Qty	Shades	Width	Height	Unit Price	Discount	Total
#1	9	Fortress Zipper Track Shade, Motorized , 3% openness	120	120	\$2968.00	-10%	\$24040.80
		Color: pebblestone					
		Regular Roll					
		Lift System: Somfy Altus 110v (left side)					
		Options: 1 5/8" Slotted Side Rails, Dark Beige 5 1/2" Housing Box					
		Notes: DEFAULT COLORS PLEASE CHOOSE COLORS. ROUGH MEASUREMENTS PLEASE TAKE FIELD MEASUREMENTS.					

Qty	Options / Accessories	Size	Unit Price	Discount	Total
1	16 Channel Hand Held Remote, White	0	\$414.00		\$414.00

Subtotal: \$24454.80
Shipping (+\$678.00): \$25132.80
Sales Tax: \$0.00
Handling: \$4.00
Total: \$25136.80

Confirm by 11/22/2013 to qualify for the Fall Coupon!

November 19, 2013
North Solar Screen
9 Bartlet Street
Suite 231
Andover, MA 01810
Phone: 866 230-4700
Fax: 978 475-6496

I, _____, authorize North Solar Screen to charge the credit card # given over the telephone. Here are the LAST FOUR DIGITS ONLY: _____, expiration date _____, to pay for this order. My signature above confirms that the materials and dimensions are correct. I understand that this custom order can't be returned, or refunded unless it is not manufactured to the specifications herein described, or the fabric or components are defective.

ALWAYS INSPECT THE CONTENTS OF YOUR SHIPMENT FOR DAMAGE WHILE THE DRIVER IS THERE. IF THERE IS DAMAGE DO NOT ACCEPT SHIPMENT OR SIGN WRITING DAMAGE SUSPECTED. IF YOU ARE NOT THERE AT DELIVERY INSPECT CONTENTS AS SOON AS YOU GET HOME AND CALL SHIPPER IMMEDIATELY IF THERE IS DAMAGE. OTHERWISE WE CANNOT FILE A CLAIM.

Any shipping damage, missing parts, or defective materials must be reported immediately.

PRODUCTION TOLERANCE +/- 1/8"

Order Notes:

We are not responsible for any measuring or installation problems arising from an installer you employ. Shipments must be inspected for damage, defects or missing parts immediately upon receipt and reported right away to North Solar Screen. If shipped to an installer it is his/her obligation to check and notify us prior to arriving at the job. We do not cover their fees.

North Solar Screen will not reimburse installers fees for any additional labor charges associated with the replacing of parts that are under warranty.

If your order is being delivered by truck IT IS YOUR RESPONSIBILITY TO MAKE SURE THAT A DELIVERY TRUCK CAN DELIVER TO YOUR ADDRESS. IN THE EVENT THAT THE TRUCKING COMPANY FINDS THAT THEY CANNOT DELIVER TO YOUR DOOR YOU WILL HAVE TO PICK UP YOUR ORDER AT THE DEPOT OR MEET THE TRUCK. IF YOU NEED TO RENT EQUIPMENT TO DO THIS IT IS YOUR RESPONSIBILITY.

Shades can be raised in windy conditions but must be lowered in calm conditions so the zipper can lock into the slots in the track.

Shades must be retracted in wind greater than 50 mph.

YOUR SAMPLES ARE IN THE MAIL. We always recommend that our customers look at physical sample swatches to make sure they are ordering the right color and fabric as computer monitors do not always reproduce color accurately. Please do not confirm until you have seen them.

Fortress Zipper Track shade installation is NOT a project for a beginning Do It Yourselfer. We recommend you work with a professional contractor. It is crucial that everything is installed level and plumb. Please view installation video. Zipper Track can withstand high winds and can be raised in high winds but should not be lowered in high winds. Clear tracks with a hose after any significant period of non-operation as debris may clog the channels and cause the shade to operate poorly or jam. FABRIC MAY EXPAND IN HOT WEATHER AND CONTRACT IN COLD WEATHER.. Operating the shades in weather significantly colder than the installation temperature when the fabric is contracted is not recommended.

November 19, 2013
North Solar Screen
9 Bartlet Street
Suite 231
Andover, MA 01810
Phone: 866 230-4700
Fax: 978 475-6496

I, _____, authorize North Solar Screen to charge the credit card # given over the telephone. Here are the LAST FOUR DIGITS ONLY: _____, expiration date _____, to pay for this order. My signature above confirms that the materials and dimensions are correct. I understand that this custom order can't be returned, or refunded unless it is not manufactured to the specifications herein described, or the fabric or components are defective.

Page 3 of 3

Your order is being shipped by SEMI truck. IT IS YOUR RESPONSIBILITY TO MAKE SURE THAT A LARGE SEMI DELIVERY TRUCK CAN DELIVER TO YOUR ADDRESS. IN THE EVENT THAT THE TRUCKING COMPANY FINDS THAT THEY CANNOT DELIVER TO YOUR DOOR YOU WILL HAVE TO PICK UP YOUR ORDER AT THE DEPOT OR MEET THE TRUCK. IF A DELIVERY IS ATTEMPTED BUT THE TRUCK CANNOT ACCESS YOUR ADDRESS AND YOU HAVE TO PICK IT UP AT THE TERMINAL YOU WILL HAVE TO PAY A REDELIVERY FEE. IF YOU NEED TO RENT EQUIPMENT TO DO THIS IT IS YOUR RESPONSIBILITY.