

**From:** Brice Gordon <[REDACTED]>

**To:** Jeffrey Epstein <jeevacation@gmail.com>

**Cc:** Larry Visoski <[REDACTED]>, Zorro Ranch <[REDACTED]>

**Subject:** ZDC LV Leak

**Date:** Thu, 11 Sep 2014 14:43:32 +0000

**Attachments:** Vent\_Pipe\_1.JPG; Vent\_Pipe\_2.JPG; Vent\_Pipe\_Boot2.JPG; Vent\_Pipe\_Boots.JPG

---

Jeffrey

Attached for your review are photo's of Vent Pipes on Larrys Roof

Before proceeding with obtaining a second option/estimate,

we thought it would best to determine location of the leak at Larry's.

We did a water test on the lower kitchen window progressing up to the upper windows, no interior leakage was found,

But we did find gaps around the vent lines.

We have installed rubber boots on the vent lines and sealed them.

Will check to see if this has resolved the problem next time we get heavy rain.

**Brice Gordon**

Ph: [REDACTED]