

From: Carlos Rodriguez <[REDACTED]>

To: Ann Rodriguez <[REDACTED]>, Jeffrey Epstein <jeevacation@gmail.com>

Subject: Little C

Date: Wed, 29 Apr 2015 13:09:10 +0000

Greetings Sir,

This morning on the way to LSJ the boat began to take on water on the starboard hull. The bilge pumps couldnt keep up and we barely made it to the dock. I truly believe the collision this boat sustained caused structural damage asides from what was repaired. The boat has a lot more flex than it used to and also the top deck and hull portions shift and flex ,this beign a secondary effect of the collision. We are taking LC to the boatyard asap to see what option we got for repair.

respectfully
Carlos