

From: Jeffrey Epstein <jeevacation@gmail.com>

To: [REDACTED]

Subject: Re: S76 update

Date: Tue, 02 Feb 2010 01:04:58 +0000

ok

On Mon, Feb 1, 2010 at 7:59 PM, <[REDACTED]> wrote:

Jeffrey,
update:

- they are installing another amp for Bass in headphones, should fix this problem.
- They are recovering the ceiling headliner do to finger print indentations I noticed, does not effect the acoustics.

only outstanding item is volume for I-Touch,
they have proposed a small volume knob to be located under I-Touch cradle.

-I will make some calls tomorrow and see if we can make the I-Touch volume work directly on the I-Touch rather than installing this knob. We have limited volume range on the Bose headset, only Medium to High for listening, which is OK,.. Keystone engineering is unable to do this due to certification issues with FAA.

would you prefer the knob? or wait till after delivery and use this as bargaining tool ?

I will have more info tomorrow.

at this time Chris said Monday it will be ready, with Bass fixed and volume knob if you choose. FYI

thanks,
Larry

--

The information contained in this communication is confidential, may be attorney-client privileged, may constitute inside information, and is intended only for the use of the addressee. It is the property of Jeffrey Epstein
Unauthorized use, disclosure or copying of this communication or any part thereof is strictly prohibited and may be unlawful. If you have received this communication in error, please notify us immediately by return e-mail or by e-mail to jeevacation@gmail.com, and destroy this communication and all copies thereof, including all attachments.