

From: [REDACTED]

To: "jeevacation@gmail.com" <jeevacation@gmail.com>

Subject: Boeing test flight

Date: Tue, 04 May 2010 15:09:24 +0000

Jeffrey,

I had to postpone my Boeing test flight,

during preflight, the #3 brake de-boost valve is leaking internally, There is an indicator that protrudes from the valve, which indicates internal bypass, new part will arrive 10am tomorrow. \$1,300 for new valve,.

de Boost valve reduces pressure from 3000 psi to 1250 psi for brake application.

I will plan on test flight after lunch tomorrow (Wednesday).

I will keep you updated

thanks,

Larry