

Bell Helicopter Miami, Inc
 2011 South Perimeter Road, Suite L
 Fort Lauderdale, Florida 33309

Phone: [REDACTED]



Hyperion Air
Invoice: C016059FL

Tuesday, August 07, 2018
 Make / Model: Bell 430
 Serial Number: 49078
 Registration: N331JE
 Total Time: 1902.2

Item	Description	Parts	Labor
PROVIDE OPERATOR ASSISTANCE			
1	Troubleshoot air conditioning system and determined temp controller failed. Replaced controller p/n 625614-1-1 s/n; 030C-11131 with repaired item same p/n; s/n; 041C-11188. Work performed with reference to BHT-430-MM Chapter 21 and 98, and BHT Report No. 4-307. Note: Work performed at operator site. No release provided by BHMI. Labor includes two trips for technician to St. Thomas.	\$25,750.00	\$7,605.00
2	Travel Expenses / Per diem	\$895.00	
2	Freight	\$65.00	\$0.00
3	This is a credit against the part posted on work order (C015714FL) as agreed between David Burch and Larry Visoski. Reference invoice IM000978FL	-\$3,892.00	
SUB-TOTAL		\$22,818.00	\$7,605.00
TOTAL		\$30,423.00	