

From: "jeffrey E." <jeevacation@gmail.com>
To: Larry Visoski <[REDACTED]>
Subject: Re: GIV
Date: Thu, 11 Jun 2015 23:04:16 +0000

if the vibration is we can upgrade the autopilots , eitherr now or when we add enhanced vision can the g4 do ny st peterburg non stop?

On Thu, Jun 11, 2015 at 6:53 PM, Larry Visoski <[REDACTED]> wrote:

Jeffrey

The GIV is return to Service,

I ground ran engines and systems check good.,

-Changed #1 ADC air data computer.,

-voltage checked left converter with digital meter: Volts, Freq and 400Hz output, heat soaked while runner for hour on ramp, checked good.

-changed two BUSS Couplers for #2 FGC Flight Guidance Computer.,nuisance item, checks good now.

-BUSS control relay fail 2 & 3 during initial power up is normal nuisance code, and can be cleared by pushing Nutcracker test switch (squat switch or WOW, Weight On Wheels) Circuit, according to HoneyWell Tech ops and SAV Tech support this is normal nuisance item,. But can be remedied by upgrade of FGC computers from our current -905 to -906 computers., system operates normal.

Our GIV has first generation SPZ8000 autopilot, GIVSP has SPZ8400 and GV had SPZ8800.,

I plan test flight in Helicopter 11am tomorrow for blade tracking.,

Possible test flight for vibration in GIV around 5pm, depends how heli flight goes,. I'll take several Gulfstream Techs to experience our buffet/vibration for opinions.,

Thx

Larry

Sent from my iPhone

--

please note

The information contained in this communication is confidential, may be attorney-client privileged, may constitute inside information, and is intended only for the use of the addressee. It is the property of JEE

Unauthorized use, disclosure or copying of this communication or any part thereof is strictly prohibited and may be unlawful. If you have received this communication in error, please notify us immediately by return e-mail or by e-mail to jeevacation@gmail.com, and

destroy this communication and all copies thereof,
including all attachments. copyright -all rights reserved