

**From:** Jeffrey Epstein <jeevacation@gmail.com>  
**To:** Richard Kahn <[REDACTED]>  
**Subject:** Re: Buck Steel  
**Date:** Tue, 25 Sep 2012 14:58:34 +0000

---

have somoen take photos of the area tdoay im not sure if far left door works

On Tue, Sep 25, 2012 at 10:33 AM, Richard Kahn <[REDACTED]> wrote:  
after speaking with Buck Steel yesterday and as you suspected the middle section of the 60' side cannot have doors as they have hurricane bracings  
is diagram below with red markings ok to proceed with  
please advise

Richard Kahn  
HBRK Associates Inc.

[REDACTED]  
tel [REDACTED]  
fax [REDACTED]  
cell [REDACTED]

Begin forwarded message:

**From:** [REDACTED]  
**Date:** September 25, 2012 10:09:04 AM EDT  
**To:** [REDACTED]  
**Subject:** Message from KMBT\_C253  
**Reply-To:** [REDACTED]

--  
\*\*\*\*\*  
The information contained in this communication is confidential, may be attorney-client privileged, may constitute inside information, and is intended only for the use of the addressee. It is the property of Jeffrey Epstein  
Unauthorized use, disclosure or copying of this communication or any part thereof is strictly prohibited and may be unlawful. If you have received this communication in error, please notify us immediately by return e-mail or by e-mail to [jeevacation@gmail.com](mailto:jeevacation@gmail.com), and destroy this communication and all copies thereof,

including all attachments. copyright -all rights reserved