

From: Richard Kahn <[REDACTED]>
To: Carlos Rodriguez <[REDACTED]>
Cc: Jeffrey Epstein <jeevacation@gmail.com>, ann rodriguez <[REDACTED]>, Stephanie Remington <[REDACTED]>, Daphne Wallace <[REDACTED]>
Subject: Sportis boat
Date: Fri, 25 Jan 2019 21:55:51 +0000

did they provide an estimate of cost?
please advise
thank you

Richard Kahn
HBRK Associates Inc.
575 Lexington Avenue 4th Floor
New York, NY 10022
tel [REDACTED]
fax [REDACTED]
cel [REDACTED]

On Jan 25, 2019, at 2:47 PM, Carlos Rodriguez <[REDACTED]> wrote:

Greetings all, These pics are from the hull of the sportis boat once the tube was completely removed by offshore. There is some delamination in the areas were the tube adheres to the boat, these need to be repaired prior to installing the tube. Offshore has their fiberglass available to start asap, to fix this and do install, please advice.
respectfully
Carlos

----- Forwarded Message -----

From: Carlos Rodriguez <[REDACTED]>
To: "[REDACTED]" <[REDACTED]>
Sent: Friday, January 25, 2019, 03:41:18 PM AST
Subject:

Sent from my iPhone

<IMG_1339.JPG><IMG_1341.JPG><IMG_1343.JPG><IMG_1344.JPG><IMG_1347.JPG>
<IMG_1348.JPG><IMG_1350.JPG>