

**From:** J <jeevacation@gmail.com>

**To:** Richard Kahn <[REDACTED]>

**Subject:** Re: Sportis boat

**Date:** Fri, 25 Jan 2019 23:37:21 +0000

---

Fix

On Fri, Jan 25, 2019 at 10:55 PM Richard Kahn <[REDACTED]> wrote:

did they provide an estimate of cost?

please advise

thank you

Richard Kahn

HBRK Associates Inc.

[575 Lexington Avenue 4th Floor](#)

[New York, NY 10022](#)

tel [REDACTED]

fax [REDACTED]

cel [REDACTED]

On Jan 25, 2019, at 2:47 PM, Carlos Rodriguez <[REDACTED]> wrote:

Greetings all, These pics are from the hull of the sportis boat once the tube was completely removed by offshore. There is some delamination in the areas were the tube adheres to the boat, these need to be repaired prior to installing the tube. Offshore has their fiberglass available to start asap, to fix this and do install, please advice.

respectfully

Carlos

----- Forwarded Message -----

**From:** Carlos Rodriguez <[REDACTED]>

**To:** "[REDACTED]" <[REDACTED]>

**Sent:** Friday, January 25, 2019, 03:41:18 PM AST

**Subject:**

Sent from my iPhone

<IMG\_1339.JPG><IMG\_1341.JPG><IMG\_1343.JPG><IMG\_1344.JPG><IMG\_1347.JPG>  
<IMG\_1348.JPG><IMG\_1350.JPG>

--

please note

The information contained in this communication is confidential, may be attorney-client privileged, may constitute inside information, and is intended only for the use of the addressee. It is the property of

JEE

Unauthorized use, disclosure or copying of this communication or any part thereof is strictly prohibited and may be unlawful. If you have received this communication in error, please notify us immediately by return e-mail or by e-mail to [jeevacation@gmail.com](mailto:jeevacation@gmail.com), and destroy this communication and all copies thereof, including all attachments. copyright -all rights reserved