

From: J <jeevacation@gmail.com>

To: Richard Kahn <[REDACTED]>

Subject: Re: Steel building

Date: Tue, 12 Mar 2019 20:00:54 +0000

Inline-Images: image003.png; image004.png; image005.png; image002.png; image006.jpg; image001.jpg

Let's get it done

On Tue, Mar 12, 2019 at 4:00 PM Richard Kahn <[REDACTED]> wrote:

not that i am aware of..

problem is that if i do not push everyone daily nothing gets done..

unfortunately lately i have been busy with banks, brokerages and hedge funds..

last emails to glidden below..

Richard Kahn

HBRK Associates Inc.

[575 Lexington Avenue 4th Floor](#)

[New York, NY 10022](#)

[REDACTED]

On Mar 12, 2019, at 3:57 PM, J <jeevacation@gmail.com> wrote:

Did we order the building steel

--

Begin forwarded message:

From: Richard Kahn <[REDACTED]>

Subject: Fwd: 40x60 bldg.

Date: March 7, 2019 at 4:15:25 PM EST

To: michael glidden <[REDACTED]>

Cc: Daphne Wallace <[REDACTED]>, Stephanie Remington <[REDACTED]>

i am not sure if you responded and i apologize if you did and i missed it..

could you please update on status and next steps as jee would like ordered asap

thank you

Richard Kahn

HBRK Associates Inc.

[575 Lexington Avenue 4th Floor](#)

[New York, NY 10022](#)

te
fa
cc
[REDACTED]

Begin forwarded message:

From: Richard Kahn <[REDACTED]>

Subject: Fwd: 40x60 bldg.

Date: February 22, 2019 at 3:25:25 PM EST

To: michael glidden <[REDACTED]>

Cc: Daphne Wallace <[REDACTED]>, Stephanie Remington <[REDACTED]>

can you please review and reply ASAP

thanks

Richard Kahn
HBRK Associates Inc.
[575 Lexington Avenue 4th Floor](#)
[New York, NY 10022](#)

tel
fax
cel



Begin forwarded message:

From: Brian Buck <[REDACTED]>
Subject: RE: 40x60 bldg.
Date: February 21, 2019 at 1:30:57 PM EST
To: michael glidden <[REDACTED]>
Cc: Daphne Wallace <[REDACTED]>, Richard Kahn <[REDACTED]>, Stephanie Remington <[REDACTED]>

Michael,

I want to put together a drawing for you but I need to clarify a couple of things first.

- So the building was not erected according to plans, it was modified somewhat in the field? The building was a fully sheeted building. So the erector opened up the left end wall to 8'2" and the back side wall to 10'6" but was sheeted 5'6" past the roof of the 14" slab. How deep is the retaining wall?
- Are the (2) 12' x 14' doors on the marked up dwg you sent back (front side wall and right end wall) to be included in these locations? Are we adding a third rollup door in bay #3 of the front side wall where you currently have a 15' rough opening?

Assuming the above is correct this is what I would propose.

We previously had the left end wall as a flush girt condition. I would change it to a bypass girt so that the girt would extend 10"(depth of girt) past the face of the column. This way a) the panel would lap over the retaining wall(if it is 10" or less deep) for a good seal and b) would allow us to shift the columns in 10'. This will clear the existing anchor bolts which will be cut off and providing the pier is sufficient in width, would save a whole lot of time and labor on those (4) left end wall columns.

I'd leave the back side wall open to 10'6", sheet above the roof and provide a wall to roof flashing. I'm assuming the slab is all even elevation?

I think if we change the bay spacings slightly(less than a foot in most cases) we can avoid having to do a lot of the demolition.

What do you think?

Regards,
Brian Buck
President



Web www.bucksteel.com
Follow us on social media!



BuckSteel



[6855 Lyons Technology Circle | Suite 18 | Coconut Creek FL 33073](#)
[1107 Battlewood Street | Suite 221 | Franklin TN 37069](#)

Legal Disclaimer: This communication and any attachments contain information which is confidential and may also be privileged. It is for the exclusive use of the intended recipient(s). If you are not the intended recipient(s) please note that any form of disclosure, distribution, copying or use of this communication or the information in it or in any attachments is strictly prohibited and may be unlawful. Where the content of this email is personal or otherwise unconnected with the firm's or its clients' business, Buck Steel accepts no responsibility or liability for such content. E-mail communications cannot be guaranteed to be secure or error free, as information could be intercepted, corrupted, amended, lost, destroyed, arrive late or incomplete, or contain viruses. We do not accept liability for any such matters or their consequences.

From: michael glidden <[REDACTED]>
Sent: Wednesday, February 20, 2019 4:56 PM
To: Brian Buck <[REDACTED]>
Cc: Daphne Wallace <[REDACTED]>; Richard Kahn <[REDACTED]>; Stephanie Remington <[REDACTED]>
Subject: Fwd: 40x60 bldg.

EFTA01030515

Good afternoon Brian.

I thought that this might help understanding how the building was installed. The only openings are as marked up.
I will gather the information tomorrow that we discussed .

Begin forwarded message:

From: michael glidden <[REDACTED]>
Subject: 40x60 bldg.
Date: February 20, 2019 at 5:47:48 PM AST
To: [REDACTED]



Sent from my iPhone

please note

The information contained in this communication is confidential, may be attorney-client privileged, may constitute inside information, and is intended only for the use of the addressee. It is the property of JEE

Unauthorized use, disclosure or copying of this communication or any part thereof is strictly prohibited and may be unlawful. If you have received this communication in error, please notify us immediately by return e-mail or by e-mail to jeevacation@gmail.com, and destroy this communication and all copies thereof, including all attachments. copyright -all rights reserved