

From: J <jeevacation@gmail.com>

To: CARLUZ TOYLO <[REDACTED]>, Richard Kahn <[REDACTED]>

Subject: Fwd: Mold inside master ductwork

Date: Mon, 25 Feb 2019 19:27:29 +0000

Attachments: IMG_0303.JPG; IMG_0304.JPG; IMG_0305.JPG

we should put a camera in to all the ducts in palm beach as wekk these are the ducts from lsj. master. yech .
merwyn same for ny

----- Forwarded message -----

From: michael glidden <[REDACTED]>

Date: Mon, Feb 25, 2019 at 2:21 PM

Subject: Mold inside master ductwork

To: <jeevacation@gmail.com>

Cc: <[REDACTED]>, Richard Kahn <[REDACTED]>, <[REDACTED]>

The light gray section is the normal color.

All the duct in the bath is now being removed also. The bath and the bedroom are separate systems.

Sent from my iPhone

--

please note

The information contained in this communication is confidential, may be attorney-client privileged, may constitute inside information, and is intended only for the use of the addressee. It is the property of JEE

Unauthorized use, disclosure or copying of this communication or any part thereof is strictly prohibited and may be unlawful. If you have received this communication in error, please notify us immediately by return e-mail or by e-mail to jeevacation@gmail.com, and destroy this communication and all copies thereof, including all attachments. copyright -all rights reserved