

From: "jeffrey E." <jeevacation@gmail.com>

To: Eric Roth <[REDACTED]>

Subject: Re: Handrails

Date: Thu, 22 Jun 2017 13:23:22 +0000

Inline-Images: image001.jpg; image009.jpg; image008.jpg; image013.jpg; image012.jpg; image003.jpg; image002.jpg; image014.jpg; image007.jpg

ok agreed

On Thu, Jun 22, 2017 at 9:21 AM, Eric Roth <[REDACTED]> wrote:

Covering it in the ultraleather is what would make it visually disappear. Any other texture and/or color highlights it.

Let me know your thoughts / decision

Best Regards,

Eric

ERIC H. ROTH | PRESIDENT

 IJI Logo - Horizontal-SMALL

P [REDACTED] | C [REDACTED] | [REDACTED] | [REDACTED]



[REDACTED] Long Island MacArthur Airport, Ronkonkoma, New York 11779

From: jeffrey E. [mailto:jeevacation@gmail.com]

Sent: Thursday, June 22, 2017 9:19 AM

To: Eric Roth <[REDACTED]>

Subject: Re: Handrails

either the same hermes. or matchiing the panel , what woudl make it disappear. ? jay last month said he had researched the tv. to see if there was an upgrade. you had said that we would need to relight the work surface if we were going to take out the rh glass. Eric. - with july 4th weekend approaching. and still no carpet sample . especially a treated one. what are your thoughts. ? I delayed putting the plane down first week in may, as agreed to accomodate your other delivery. i need an accurate timeframe TODAY. !!! you told me may 5 th that the door would be looked at while the place was there. . I am understanding re real life issues. that being said accurate dates like the added list only produced yesterday that says 3500 dollars to recover the potty seat.?? with foam has been promised for over a month. .

On Thu, Jun 22, 2017 at 9:12 AM, Eric Roth <[REDACTED]> wrote:

[What fabric are you thinking of?](#)

As you can see in the photo below, the headliner and PSU's are in ultraleather.



Best Regards,

Eric

ERIC H. ROTH | PRESIDENT

 IJI Logo - Horizontal-SMALL

P [REDACTED] | C [REDACTED] [REDACTED] [REDACTED]  

[REDACTED] Long Island MacArthur Airport, Ronkonkoma, New York 11779

From: jeffrey E. [mailto:jeevacation@gmail.com]
Sent: Wednesday, June 21, 2017 7:24 PM
To: Eric Roth <[REDACTED]>
Subject: Re: Preliminary for review

hand rails in fabric not ultraleather . price issues to be discussed with rich and larry,

On Wed, Jun 21, 2017 at 5:49 PM, Eric Roth <[REDACTED]> wrote:

Jeffrey,

As per our discussion a few minutes ago, I did not include the work TBD on the pocket door for the cabin side.

CHANGE ORDER ITEMS REQUESTED

316 Fwd Lavatory Door \$ 870

Design and fabricate a wood veneer overlay cover for the vacant / occupied sign to make it aesthetically blend in with the interior and not make it so conspicuously obvious. The cover will have one (1) hole that will display either color green (for vacant) or red (for occupied) and a thin horizontal slot for the lock override pin.

317 Fwd Crew Galley \$ 15,780

Remove the existing hot water container and associated wiring. Modify the space to accept a customer supplied carry on small coffee maker (loose equipment). Relocate existing drawer if possible. All interior surfaces to be painted to match existing. Install new 110v 60Hz provisional outlet and associated wiring.

404 Hand Rails \$ 4,820

Unfasten the cabin area PSU / valence assemblies to gain access to the wood veneered hand rails. Remove the hand rails from the PSU assemblies. Prep and cover the hand rails in the same ultraleather material as the PSU's to match. Reinstall newly covered hand rails and reinstall PSU assemblies.

412 Fwd Cabin Bulkheads \$ 5,060

Remove the two (2) leather covered seat belt bumper pads. Template and fabricate thin kydex overlay panels. Cover panels in Hermes fabric to match the lower side walls. Remove and

reinstall existing magazine racks (R/H has cabin temp sensor). Relocate any required placards and ash tray.

413 Fwd Cabin Door \$

420 Cabin Single Seats \$ 18,190

Relocate the R/H #2 and L/H #2 seats approximately 4.0" aft to increase leg room. Install seat track as required including engineering and certification. Close off floor decompression blow out panel at R/H #3 seat position and install one (1) decompression blow out panel in the cabin area. Relocate the existing subwoofer from L/H #3 seat position.

423 Divan End Arm Cabinets \$ 20,350

Design and fabricate light weight composite "sleeve" to fit over the four (4) existing end arm cabinets. Increase the height of the four (4) end arm cabinets by approximately 3.0" – 4.0". Angle the inside of each arm rest starting at the top of the bottom cushions as a decorative feature. Relocate existing Cabin Management Switches to the outboard side of the arm rests to create a clean inboard end arm(s).

503 Aft L/H Galley (Coffee Makers) \$ 2,920

Remove the existing dual coffee makers from the upper galley area. Finish out area to conceal all non-essential wiring / plumbing / etc. Cap and stow existing electrical wiring and plumbing for the coffee makers. New interior surfaces painted to match the existing laminate.

503 Aft L/H Galley (Oven) \$ 2,920

Remove the existing oven from the lower galley area. Finish out area to conceal all non-essential wiring / plumbing / etc. Cap and stow existing electrical wiring for the oven. New interior surfaces painted to match the existing laminate.

606 Aft Lavatory Potty Seat & Shroud \$ 3,210

Laminate an additional .75" foam to the top of the potty seat for additional comfort. Laminate the potty seat deck with high gloss white high pressure laminate. Prep and paint toilet seat ring high gloss white to match new laminate.

611 R/H Aft Lavatory Closet \$ 2,560

Modify closet by fabricating and installing a recessed cavity toilet paper holder. Inside of cavity will be laminated in wood veneer. Finish wood veneer in a high build finish.

Best Regards,

Eric

ERIC H. ROTH | PRESIDENT

LJI Logo - Horizontal-SMALL

P [REDACTED] | C [REDACTED] [REDACTED] [REDACTED]



[REDACTED], Long Island MacArthur Airport, Ronkonkoma, New York 11779

--

please note

The information contained in this communication is confidential, may be attorney-client privileged, may constitute inside information, and is intended only for the use of the addressee. It is the property of JEE

Unauthorized use, disclosure or copying of this communication or any part thereof is strictly prohibited and may be unlawful. If you have received this communication in error, please notify us immediately by return e-mail or by e-mail to jeevacation@gmail.com, and destroy this communication and all copies thereof, including all attachments. copyright -all rights reserved

--

please note

The information contained in this communication is confidential, may be attorney-client privileged, may constitute inside information, and is intended only for the use of the addressee. It is the property of JEE

Unauthorized use, disclosure or copying of this communication or any part thereof is strictly prohibited and may be unlawful. If you have received this communication in error, please notify us immediately by return e-mail or by e-mail to jeevacation@gmail.com, and destroy this communication and all copies thereof, including all attachments. copyright -all rights reserved

--

please note

The information contained in this communication is confidential, may be attorney-client privileged, may constitute inside information, and is intended only for the use of the addressee. It is the property of JEE

Unauthorized use, disclosure or copying of this communication or any part thereof is strictly prohibited and may be unlawful. If you have received this communication in error, please notify us immediately by

return e-mail or by e-mail to jeevacation@gmail.com, and
destroy this communication and all copies thereof,
including all attachments. copyright -all rights reserved