

**From:** "jeffrey E." <jeevacation@gmail.com>  
**To:** Larry Visoski <[REDACTED]>  
**Subject:** Re: Nautica  
**Date:** Wed, 15 Feb 2017 21:28:16 +0000

---

great, please show me a photo of the aft side of boat, do we need to put abother bench seat acorss the rear?

On Wed, Feb 15, 2017 at 4:25 PM, Larry Visoski <[REDACTED]> wrote:

Jeffrey

Good news,, we only Spun the prop hub on one engine,,  
It's the rubber insert in prop,, so there is no internal issue with engine,,  
Need 02 sensors change in engines and small tune up and update for computer,,

Sent from my iPhone

--

please note

The information contained in this communication is confidential, may be attorney-client privileged, may constitute inside information, and is intended only for the use of the addressee. It is the property of JEE

Unauthorized use, disclosure or copying of this communication or any part thereof is strictly prohibited and may be unlawful. If you have received this communication in error, please notify us immediately by return e-mail or by e-mail to [jeevacation@gmail.com](mailto:jeevacation@gmail.com), and

destroy this communication and all copies thereof,  
including all attachments. copyright -all rights reserved