

Reefco Services, Inc.

St. Thomas, VI, 00802-6463

# Invoice

|          |           |
|----------|-----------|
| Date     | Invoice # |
| 8/7/2015 | 109459    |


|                    |
|--------------------|
| <b>Bill To</b>     |
| Little Saint James |

|                |
|----------------|
| <b>Ship To</b> |
|                |

| P.O. Number        | Terms          | Rep | Ship     | Via | F.O.B. | Project |
|--------------------|----------------|-----|----------|-----|--------|---------|
| Little Saint James | Due on receipt | TG  | 8/7/2015 |     |        |         |

| Quantity   | Item Code | Description                              | U/M | Price Each | Amount |
|--|-----------|--|-----|------------|--------|
| 6  | 2001      | Labor Air-Conditioning and Refrigeration |     | 101.00     | 606.00 |
| 6  | H1        | Regular Time Helper A/C & Refrig         |     | 50.00      | 300.00 |
| <p>Repaired ductwork to carpenter shop. Closed holes cut into ductwork by workers. Carpenter shop now cooling.</p> <p>Tried to restart Gymnasium unit (Rheem) which had thawed overnight (found frozen during previous day PM). Cleaned coil, checked pressure-found very low. Inspected evaporator coil-found extremely rusted. Sent photo's to Anna. She requested quote for new equipment. Air handler and condensing unit in deteriorated condition. Advise replacing.</p> |           |  |     |            |        |

|   |       |                          |         |       |        |  |  |                          |              |          |
|---|-------|--------------------------|---------|-------|--------|--|--|--------------------------|--------------|----------|
| <table border="1"> <tr> <td>Phone #</td> <td>Fax #</td> <td>E-mail</td> </tr> <tr> <td> </td> <td> </td> <td>reefcoservices@gmail.com</td> </tr> </table> |       |                          | Phone # | Fax # | E-mail |  |  | reefcoservices@gmail.com | <b>Total</b> | \$906.00 |
| Phone #   | Fax # | E-mail                   |         |       |        |  |  |                          |              |          |
|   |       | reefcoservices@gmail.com |         |       |        |  |  |                          |              |          |



# REEFCO SERVICES, INC

Marine Refrigeration & Air Conditioning  
Reverse Osmosis Desalination Systems

109459

3801 Crown Bay, Suite 210  
St. Thomas USVI 00802  
Phone/Fax: [REDACTED]  
E: reefcoservices@gmail.com

|                                    |  |                        |                   |
|------------------------------------|--|------------------------|-------------------|
| NAME/VESSEL/HIN#<br>LSJ island     |  | DEPT.<br>01            | DATE<br>Aug 7/15  |
| CONTACT/PHONE #<br>ANNA [REDACTED] |  | LOCATION<br>LSJ island |                   |
| BRAND NAME                         | MODEL #  | SERIAL #               |                   |
| TECH<br>Tom                        | PAYMENT TYPE   | AUTH. #                |                   |
|                                    |  |                        |                   |
|                                    |  |                        |                   |
|                                    | Tried to Restart GYMNASIUM UNIT RHEEM, which had thawed over night (found FROZEN FROM PREVIOUS DAY) cleaned coil   |                        |                   |
|                                    | checked pressure found very low. inspected EVAPORATOR COIL, found EXTREMELY RUSTED                                 |                        |                   |
|                                    | Sent PHOTO'S TO ANNA.  |                        |                   |
|                                    | She Requested Quote For New EQUIPMENT. Air Handler and CONDENSING UNIT IN DETERIORATED CONDITION. Advise Replacing |                        |                   |
|                                    | 6 Hours Tech   | 101 <sup>00</sup>      | 606 <sup>00</sup> |
|                                    | 6 Hours Helper Labor   | 50 <sup>00</sup>       | 300 <sup>00</sup> |
|                                    | Repaired Ductwork TO   |                        |                   |
|                                    | (*) Carpenter Shop. Closed Holes   |                        |                   |
|                                    | CUT INTO Ductwork BY   |                        |                   |
|                                    | Workers. Carpenter Shop NOW COOLING.   | \$                     | 906 <sup>00</sup> |

SIGNATURE

WE APPRECIATE YOUR BUSINESS  
[www.reefco.net](http://www.reefco.net)