

**From:** "Emad Hanna" <[REDACTED]>  
**To:** "Jeffrey Epstein" <je[REDACTED]>  
**Subject:** Pictures  
**Date:** Tue, 14 Dec 2010 22:28:04 +0000

**Attachments:** 12-14-10\_Laundry\_Room\_Dryer\_Vent.jpg; 12-14-10\_Laundry\_Room\_Dryer\_Vent1.jpg; 12-14-10\_Master\_Bedroom\_Primer1.jpg; 12-14-10\_Master\_Bedroom\_Primer2.jpg; 12-14-10\_Master\_Bedroom\_Primer3.jpg; 12-14-10\_Master\_Bedroom\_Primer4.jpg; 12-14-10\_Master\_Bedroom\_Road\_Fish\_Tails.jpg; 12-14-10\_Master\_Bedroom\_Road\_Fish\_Tails2.jpg; 12-14-10\_Master\_Bedroom\_Road\_Coconut.jpg

---

Jeffrey,

The laundry room dryer vent in the 1<sup>st</sup> two pictures show the cutting of the electrical conduit for the AC which [REDACTED] told if someone had looked out side on the roof this would have been noticed and maybe avoided?

Igala was missing 6 of his crew members today due to vacation and one working the barge and another helping Brian.

Thank you

Emad Hanna  
Project Controller  
HBRK Associates  
301 East 66th St  
Suite 10F  
New York, NY 10065  
Cell (340) 642-8763  
LSJ Office (340) 775-8127  
St. Thomas Office (340) 775-2525  
NY Office (646) 862-4815  
Fax (646) 350-0221  
[REDACTED]