

CILMI & ASSOCIATES PLLC

Attorneys and Counsellors at Law

Thirty-Nine Broadway
Twelfth Floor
New York, New York 10006
Tel: [REDACTED] Fax: [REDACTED]
www.cilmilaw.com

2040 Victory Boulevard
Staten Island, New York 10314

313 South Avenue
Suite 204
Fanwood, New Jersey 07023
[REDACTED]

Sender's email:
NPUSEY@[REDACTED]

July 13, 2011

Via Overnight Courier

Darren K. Indyke, PLLC
301 East 66th Street, 10B
New York, New York 10065
Attn: Darren K. Indyke, Esq.

Re: 12-14 East 72nd Street Residential Construction Project
Complaint re: 9 E.71st Street

Dear Mr. Indyke:


We are in receipt of your letter, dated July 10, 2011, in which you advise your client is experiencing certain conditions in purported connection with the work our client is performing at their East 72nd Street project.

While we are in the process of seeking all information relating to your client's complaint, it appears from a preliminary review of materials and data available that the equipment used to monitor activity during the excavation phase report readings within acceptable parameters. Should our further investigation into this matter unearth anything to contradict the above, our client and their representatives, contractors and subcontractors will take all appropriate measures.

Should you have any additional information you would like to share, we would appreciate your forwarding such information to our attention. Please call me should you have any questions.

Thank you.

Very truly yours,
CILMI & ASSOCIATES PLLC


Noah L. Pusey