



Estimate

| Date | P.O./ Sub. Num | Due Date | Estimate # |
|-----------|----------------|------------|------------|
| 9/14/2015 | | 10/14/2015 | ██████████ |

| Project | Prepared by |
|--------------------|-------------|
| 9 East 71st Street | LZ |

| |
|----------------|
| Name / Address |
| Calrity AV |

| Code | Item | Qty | Description | Cost | Total |
|---------------|-------|-----|--|----------|----------|
| scope of work | LABOR | | - providing support (up to 150 lb) and installing sculpture on 1st floor staircase - plastering and painting by others - scaffold/lift by others - protection to be done by others - any additional custom finish hardware is not included (if needed will be additional charge) | 2,800.00 | 2,800.00 |

This quote is valid only for 30 days. If there are changes, the quotation will be void. Quote subject to manufacturer's published terms and conditions of sale. Payment schedule: 25% deposit of contract upon start-up; 50% deposit on all fixtures; Monthly progress payments thereafter.

| | |
|--------------|------------|
| Total | \$2,800.00 |
|--------------|------------|

| |
|------------|
| Phone # |
| ██████████ |

| |
|------------|
| Fax # |
| ██████████ |

| |
|------------|
| E-mail |
| ██████████ |

| |
|------------|
| Web Site |
| ██████████ |

