



Omega Container Services, Inc.

P.O. Box 660006

Miami Springs, FL 33266-0006

Tel: [REDACTED]

BILL OF SALE

Date	Invoice #
8/23/2018	18-8686

Bill To

LSJE, LLC - St. Thomas  
6100 Red Hook Quarter B3  
St. Thomas, VI 00802-1348

Ship To

EXPORT  
Bill of Lading Required

Qty	Description	Rate	Amount
1	20' Container (Unpainted)  Unit # 364921-0  CSC Certified & Updated	1,700.00	1,700.00

8/23/18  
Credit Card Processed  
Awaiting Funds

AS ALWAYS, THANK YOU FOR YOUR BUSINESS.	<b>Total</b> \$1,700.00
---	-------------------------

THE EQUIPMENT/GOODS COVERED BY THE CONTRACT HAVE BEEN PURCHASED BY THE BUYER 'AS IS' AND THE BUYER ACKNOWLEDGES THAT NO WARRANTIES OF MERCHANTABILITY OR FITNESS FOR ANY PARTICULAR PURPOSE ARE TO BE IMPLIED IN THIS TRANSACTION. THE SELLER GIVES NO WARRANTY, EXPRESS OR IMPLIED, AS TO DESCRIPTION, QUALITY, OTHER MATTER, OF ANY EQUIPMENT/GOODS WHICH THE SELLER SHALL SUPPLY. THE SELLER SHALL BE IN NO WAY RESPONSIBLE FOR THEIR PROPER USE AND SERVICE, AND THE BUYER HEREBY WAIVES ALL RIGHTS OF REFUSAL AND RETURN OF GOODS. ALL PURCHASES MUST BE PAID WITHIN 15 BUSINESS DAYS AFTER THE DATE OF THE INVOICE, IF NOT, THE INVOICE WILL BE CONSIDERED VOID.

BY: \_\_\_\_\_  
PURCHASER

# Omega Container Services, Inc.

8811 NW 93<sup>rd</sup> Street  
Medley, FL 33178

Tel: [REDACTED] Fax: 305-883-1272



## CSC Safety Survey:

**THIS IS TO CERTIFY** that **Daniel Perez**, a trained survey inspection technician, inspected the below referenced ISO container and found it to be water-tight, the corner casting are square, and it is sufficiently sound to meet the rigors of an ocean voyage.

Unit NO: **364921-0**

Party Requesting Survey: **LSJE, LLC - St. Thomas**

Location of Inspection: **8811 NW 93<sup>rd</sup> Street**

Equipment Owner: **LSJE, LLC - St. Thomas**  
**6100 Red Hook Quarter B3**  
**St. Thomas, VI 00802-1348**

The Container is: FIT  NOT FIT  *to carry general cargo*

Length of Unit: 20'  20' HC  40' STD  40' HC  45' HC

Container Type: Dry  Refrigerated  Other

Container: Steel  Aluminum  FRP

MANUFACTURE DATE & COUNTRY: **09/2007** (China)

A valid CSC plate is attached to the container.

ACEP/CSC Sticker Date: **8/2019**

An outdated CSC plate is attached to the container.

The container does not have a CSC plate attached.

Max Gross Weight: **30,480KG/67,200LB**

Tare Weight: **2,200KG /4,890LB**

## REMARKS:

Inspection Date: **08/23/2018**

Stamp:

**Daniel Perez**

IICL Certificate #: 130742

Expiration Date: 12/31/18  
Registration #: 080700

Tax ID #: 65-0060697

IICL Certified Date: **January 1, 2009**

Inspected By: \_\_\_\_\_

(Signature)

Print Name: **Daniel Perez**

Company: **Omega Container Services**

Address: **8811 NW 93<sup>rd</sup> Street**

City: **Medley**

State: **Florida** Zip Code: **33178**

Telephone: [REDACTED]

Fax: [REDACTED]